



inspection report

- Partial
- Complete
- Exploration

Inspection Date: March 16, 1994
 Time: 8:30 am pm to 3:30 am pm
 Date of Last Inspection: February 25, 1994

Mine Name: Starpoint County: Carbox Permit Number: Act 007/006

Permittee and/or Operator's Name: Cypress Mining Corporation

Business Address: P.O. Drawer, Pella, Puce, Utah 84501

Type of Mining Activity: Underground Surface Prep. Plant Other

State Official(s): Bill Malencik

Company Official(s): Ralph Mooseman

Federal Official(s): N/A

Weather Conditions: Clear - Snow on N slopes

Existing Acreage: Permitted- 1200 Disturbed- 220 Regraded- Seeded- Bonded- 220

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 007/006

Inspection Date 3/16/94

Please number comments to correspond with topics on previous page.

General Comments. Ground conditions on the lower mine site is again conducive to the routine performance of maintenance work. The operator has started his spring cleanup.

Drainage. Suggest several drainages be given touch up maintenance included culverts when the ice melts.

Sediment Ponds. Observed sediment ponds 2, 3, 4, 6, 7, 8, & 9. All ponds except sediment pond 7 contained runoff. Pond #3 was covered in part with a layer of ice. None of the ponds noted above were discharging at the time of the inspection.

Other Sediment Control. Observed silt fences at the Silo B/CA area. All were functional. One showed recent evidence of detouring runoff.

Roads. The county road via #1 mine to mine office is inaccessible by vehicle because of snow drifts on the north facing slope. All primary roads were free from snow. The ancillary road to sediment pond 4 was wet from melting snow.

Suggestion. Continue spring maintenance as soon as ground conditions are suitable.

Copy of report mailed to Starpaint/ Ben Quinlan; OSM/Marcia Patta; DOGM/ Joe Heltrich

Copy of report given to RFO

Inspector's signature Tom J. Malinich

No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/ OPERATOR GOLDENROD - NOV FILE

3/21/94