



inspection report

- Partial
- Complete
- Exploration

Inspection Date: April 18, 1995  
 Time: 1 : 00  am  pm to 4 : 00  am  pm  
 Date of Last Inspection: March 2, 1995

Mine Name: Starpoint County: Caban Permit Number: Act 007/006

Permittee and/or Operator's Name: Cypress Mining Corporation

Business Address: P.O. Drawer, PMC, Price, UT, 84501

Type of Mining Activity:  Underground  Surface  Prep. Plant  Other

State Official(s): Bill Malencik

Company Official(s): John Pappas

Federal Official(s): N/A

Weather Conditions: Snowing

Existing Acreage: Permitted- 7200 Disturbed- 220 Regraded- \_\_\_\_\_ Seeded- \_\_\_\_\_ Bonded- 220

Increased/Decreased: Permitted- \_\_\_\_\_ Disturbed- \_\_\_\_\_ Regraded- \_\_\_\_\_ Seeded- \_\_\_\_\_ Bonded- \_\_\_\_\_

Status:  Exploration /  Active /  Inactive /  Temporary Cessation /  Bond Forfeiture  
 Reclamation ( Phase I /  Phase II /  Final Bond Release /  Liability \_\_\_\_\_ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTORPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) <u>April 18</u> (date) <u>1995</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 007/006

Inspection Date 4/18/95

Please number comments to correspond with topics on previous page.

General Conducted a partial inspection of the Starpoint mine, John Pappas represented the permittee.

The mine received about a foot of snow the night of 4/17/95. When departing the mine site about 4 pm it was snowing heavily.

The areas covered in this inspection included the coal train loadout, tippie and office pad.

Because of weather conditions it was difficult to make any judgements on most environmental control measures. However, since the last inspection road ditches and the upper primary road has been cleaned of rocks and regraded. Also work had been completed in regrading pad areas near the fuel tanks.

Amendments The most recent amendment dated 3/7/95, submitted by the permittee concerned replacing a 12" culvert with a 24" culvert. The permittee submitted Table 742d, page 700-135 which contains design data. The culvert will be oversized since the calculations only require a 12" culvert.

The foregoing amendment was approved by the undersigned on March 29, 1995

Copy of report mailed to \_\_\_\_\_

Copy of report given to \_\_\_\_\_

Inspector's signature \_\_\_\_\_ No. \_\_\_\_\_

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act 007/006

Inspection Date \_\_\_\_\_

Please number comments to correspond with topics on previous page.

Diversion Since the last inspection the operator has performed routine maintenance on several Diversion in the vicinity of the wash plant impoundments

Sediment Ponds Observed ponds 8 and 9, Neither pond was discharging. All ponds contained runoff.

Other Sediment Control Measures Observed silt fences on the outslope of the coal silo. They appear to be functional and effective in treating runoff from this small disturbed area.

Reture Pile Snow conditions have added to wet conditions at the Reture pile. When weather and site conditions are propitious, the pile needs to be surveyed in order to be assured that the top of the pile has positive grade and adequate drainage.

Roads Roads were not covered with snow i.e., the primary roads had snow removed from the surface portion of the road.

AUS Starpoint submitted updated AUS information to the Division this reporting period.

Copy of report mailed to CPMC/John Pappas; DSM/Donna Griffin; DOGM/Joe Helfreich

Copy of report given to filed Reice Field Office

Inspector's signature [Signature]

No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE