

### Document Information Form

Mine Number: C1007/006

File Name: Incoming

To: DOGM

From:

Person N/A

Company N/A

Date Sent: N/A

Explanation:

1998 ANNUAL REPORT REVIEW

cc:

File in:  
C/ 007, 006, Incoming

- Refer to:
- Confidential
  - Shelf
  - Expandable

Date \_\_\_\_\_ For additional information

Original: 007/006 #6  
 CC: E 11

## 1998 Annual Report Review

Permittee: Cyprus Plateau Mining  
 Mine Name: Star Point Mine  
 Permit Number: ACT/007/006  
 Date Report Received: 05/14/99  
 Assigned Reviewers: Bill Malencik, Wayne Western, Susan White  
Dave Darby

**Instructions:** The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine folder #6.

**Assignments:**  
**Inspectors:** Review cover sheet, AVS legal/financial, Mine sequence map  
**Hydrologists:** Review water monitoring data, Precipitation and climatological data, Non-coal waste  
**Biologists:** Review vegetation/revegetation success monitoring, Raptor survey  
**Engineers:** Review subsidence monitoring data, Annual impoundment certification, Annual overburden, spoils, refuse, floor, etc.

Section to review	Submitted Yes	No	Findings
Cover sheet	<u>X</u>	—	
AVS; Legal/Financial Update	<u>X</u>	—	
Mine Sequence Map	<u>X</u>	—	The 1998 MSHA map was included. That map shows the areas where mining has occurred.
Water Monitoring Data	<u>X</u>	—	Water monitoring and quality data submitted monthly and quarterly
Precipitation & Climatological Data	<u>X</u>	—	Precipitation data submitted in mine plan as baseline information
Non-Coal Waste report	—	<u>X</u>	This information is discussed in the MRP on Page 500-55. Non-coal will not be stored on site, it will be collected in bins then disposed of by contractor to permitted disposal site.

**File in:**

- Confidential
- Shelf
- Expandable

Refer to Record No. 0031 Date \_\_\_\_\_  
 In C/ 007, 006, Incoming

For additional information

Subsidence monitoring data	<u>X</u> —	No major impacts were reported in 1998. The Division's biologist should review the section of the subsidence report that describes vegetation.
Annual Impoundment Certification	<u>X</u> —	All ponds are in proper working order.
Annual Overburden, Spoil, Refuse, Floor, etc.	<u>X</u> —	The refuse pile is in proper working order.
Vegetation data	<u>X</u> —	A report interpreting the results of color infrared photography of the vegetation was included. This is required every 5 years. The report concluded that potentially 3 springs appeared drier and therefore were potentially affected. The Operator should further address this issue.
Revegetation Success monitoring	<u>X</u> —	
Raptor survey	<u>X</u> —	A list of nest status from the 1998 raptor survey was submitted in the annual report.
Other information	<u>X</u> —	The Operator states that a copy of the Macroinvertebrate Report has been requested several times from the USFS. When they receive a copy it will be forward to the Division.

O:\007006.STP\ANNUALRP\REVIEW.FRM