

INSPECTION REPORT

Partial Complete Exploration
 Inspection Date: 07/10/2003/ Time: 8:00 – 14:00
 Date of Last Inspection: 06/10/2003

Mine Name: Star Point Mine County: Carbon Permit Number: C/007/006
 Permittee and/or Operator's Name: Plateau Mining Corporation
 Business Address: P.O. Box 30, Helper, Utah 84526
 Company Official(s): Johnny Pappas
 State Official(s): Karl R. Houskeeper Federal Official(s): None
 Weather Conditions: Clear, Temp 96°F
 Type of Mining Activity: Underground XXX Surface Prep Plant Other
 Existing Acreage: Permitted 9084 Disturbed 213.4 Regraded Seeded
 Status: Active Reclamation

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/006

DATE OF INSPECTION: 07/10/2003

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The DOGM Permit was effective on 01/28/2002 and expires on 01/27/2007. Other documents include the following:

- Certificate of Insurance terminates 01/01/2004.
- Reclamation Agreement is dated July 1999.
- UPDES Permit UT0023736 effective 01/01/2002 and expires midnight 12/31/2006.
- Air Quality Permit DAQE-886-96 issued 09/20/1996.

2. SIGNS AND MARKERS

The ID sign is located at the public access to the permit boundary. The refuse pile sign is located at the entrance to the pile and contained the proper information. Other markers observed during the inspection were in place as required by the coal rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

First and second quarter 2003 sediment pond inspections were conducted on 03/31/03 and 06/04/03 respectively. No hazards or stability problems were noted on the inspection forms.

4D. HYDROLOGIC BALANCE: WATER MONITORING

First quarter 2003 water monitoring information was uploaded into the EDI website on May 6, 2003. Water monitoring is current.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

Reviewed the DMR's for May 2003 from Plateau Mining Corporation. No discharge occurred since all of the outfalls listed on UPDES permit Ut0023736 have been reclaimed.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

First and second quarter 2003 refuse pile inspections were P.E. Certified on 03/05/03 and 06/07/03 respectively. Haulage records of the amount of refuse removed by SCA are as follows:

- March 2003, 34,055 tons of refuse removed and hauled to SCA.
- April 2003, 12,330 tons of refuse removed and hauled to SCA.
- May 2003, 20,835 tons of refuse removed and hauled to SCA.
- June 2003, 37,575 tons of refuse removed and hauled to SCA.
- July 2003, 5,265 tons of refuse removed to date and hauled to SCA.

10. SLIDES AND OTHER DAMAGE

Tension cracks and vertical displacement are present on the reclaimed slope of the Lions Deck. The cracks and displacement are being monitored. The tension cracks are a result of material settling within the old surge bin. The surge bin was used to drop the coal from the Lions Deck to a lower level.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/007/006

DATE OF INSPECTION: 07/10/2003

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Sections of the county road leading to the Lions Deck that were repaired have now been asphalted.

20. AIR QUALITY PERMIT

The Air Quality Permit DAQE-886-96 was issued on 09/20/1996 and remains in effect.

21. BONDING AND INSURANCE

The current bonds on record are as follows:

- Bond #KA2990-096 for \$3,527,000.
- Bond #210067-096 for \$3,527,000.
- Bond #103198931-096 for \$3,527,000.

The total bonded amount is \$10,581,000. The reclamation agreement remains in effect.

The insurance is provided through Aon Risk Services, Policy # ICH GL 137-02. The insurance meets the minimum requirements and includes explosion coverage. The policy expires on 01/01/2004.

Inspector's Signature: _____ Date: July 10, 2003
Karl R. Houskeeper #49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Johnny Pappas, Plateau, via email
Price Field office
O:\007006.STP\Compliance\2003\c_0710.doc