From: Steve Demczak
To: Dennis Ware; Suzanne Steab
Date: 9/29/2010 8:26 AM
Subject: Sept Insp.
Attachments: 20100929084341.pdf; 20100929084407.pdf; 20100929084318.pdf

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Inspection Report

Representatives Present During the Inspection:	
Company	Dennis Ware
OGM	Steve Demczak

Permit Number:	C0070006
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, September 22, 2010
Start Date/Time:	9/22/2010 2:00:00 PM
End Date/Time:	9/22/2010 4:00:00 PM
Last Inspection:	Thursday, August 26, 2010

Inspector: Steve Demczak,

Weather: Cloudy, 60's, Rain Drizzle

InspectionID Report Number: 2510

Accepted by: jhelfric
9/28/2010

Permitee: **PLATEAU MINING CORP**
Operator: **PLATEAU MINING CORP**
Site: **STAR POINT MINE**
Address: **PO BOX 30, HELPER UT 84526-0030**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **RECLAIMED**

Current Acreages

8,885.00	Total Permitted
87.30	Total Disturbed
95.30	Phase I
95.30	Phase II
8.00	Phase III

Mineral Ownership

- [x] Federal
- [x] State
- [ ] County
- [x] Fee
- [ ] Other

Types of Operations

- [x] Underground
- [ ] Surface
- [ ] Loadout
- [ ] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature: Stephen J Demczak **Date** Monday, September 27, 2010

Steve Demczak,
Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 *www.ogm.utah.gov*

Utah! *Where ideas connect*

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☑	☐	☑	☐
4.a Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☐	☑	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☑	☐	☑	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☐	☐	☐	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☑	☐	☑	☐
10. Slides and Other Damage	☑	☐	☑	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☑	☐	☑	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

The identification sign is next to the road to the site. The permittee has removed the subsidence markers from the permit area.

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

Diversions were spot-checked and were functioning as designed.

4.c Hydrologic Balance: Other Sediment Control Measures

The complete site is pocked to prevent sediment from leaving the reclaimed area.

8. Noncoal Waste

The site was clear of non-coal waste material.

9. Protection of Fish, Wildlife and Related Environmental Issues

Occasionally deer can be seen grazing on the hillside.

10. Slides and Other Damage

No slides or other damage were noticed during the inspection

12. Backfilling And Grading

The disturbed area is completely backfilled and graded. The permittee received Phase II bond release from the Division.