

**From:** Steve Demczak  
**To:** Dennis Ware; Suzanne Steab  
**Date:** 8/1/2011 1:46 PM  
**Subject:** Fwd: Attached Image  
**Attachments:** Attached Image

Outgoing  
CO070004  
CO070006  
CO070038  
K



GARY R. HERBERT  
Governor

GREG BELL  
Lieutenant Governor

# State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

## Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0070006
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, July 19, 2011
Start Date/Time:	7/19/2011 8:00:00 AM
End Date/Time:	7/19/2011 10:00:00 AM
Last Inspection:	Wednesday, June 22, 2011

Inspector: Steve Demczak

Weather: Sunny, 80's

InspectionID Report Number: 2808

Accepted by: jhelfric

7/28/2011

Representatives Present During the Inspection:

- OGM Karl Houskeeper
- OGM Steve Demczak

Permittee: **PLATEAU MINING CORP**  
 Operator: **PLATEAU MINING CORP**  
 Site: **STAR POINT MINE**  
 Address: **PO BOX 30, HELPER UT 84526-0030**  
 County: **CARBON**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **RECLAIMED**

### Current Acreages

8,885.00	Total Permitted
87.30	Total Disturbed
95.30	Phase I
95.30	Phase II
8.00	Phase III

### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

*Steve Demczak*  
Steve Demczak

Inspector ID Number: 39

Date

Thursday, July 28, 2011



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**2. Signs and Markers**

The identification sign is next to the road to the site. The permittee has removed the subsidence markers from the permit area.

**3. Topsoil**

All topsoil was used for reclamation.

**4.a Hydrologic Balance: Diversions**

The diversions were stable and open. Some grasses are growing within the diversion.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The complete site is pocked to prevent sediment from leaving the reclaimed area.

**8. Noncoal Waste**

The site is clear of non-coal waste materials.

**10. Slides and Other Damage**

No slides were noticed during the inspection.

**12. Backfilling And Grading**

The site is completely backfilled and graded to AOC.

**13. Revegetation**

Small pine trees are coming up on the upper bench area. The pine trees are native to the area.

**16.a Roads: Construction, Maintenance, Surfacing**

The County has the road through the property and does road maintenance.

**18. Support Facilities, Utility Installations**

There are no facilities at Starpoint.



GARY R. HERBERT  
Governor

GREG BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number:	C0070038
Inspection Type:	PARTIAL
Inspection Date:	Thursday, July 14, 2011
Start Date/Time:	7/14/2011 2:00:00 PM
End Date/Time:	7/14/2011 4:00:00 PM
Last Inspection:	Wednesday, June 22, 2011

Inspector: Steve Demczak

Weather: Sunny, 80's

InspectionID Report Number: 2805

Accepted by: jhelfric

7/28/2011

Permittee: **PLATEAU MINING CORP**

Operator: **PLATEAU MINING CORP**

Site: **WILLOW CREEK MINE**

Address: **PO BOX 30, HELPER UT 84526-0030**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

#### Current Acreages

14,662.49	<b>Total Permitted</b>
71.44	<b>Total Disturbed</b>
125.41	<b>Phase I</b>
92.45	<b>Phase II</b>
92.45	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division that the first quarter of 2011 surface and UPDES water monitoring information for the Willow Creek Mine was in the electronic data base pipeline ready for uploading.

The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit, which was renewed April 24, 2011.

There are no pending compliance actions.

There is currently no activity at this site.

Inspector's Signature:

Steve Demczak,

Inspector ID Number: 39

Date Wednesday, July 14, 2011



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**2. Signs and Markers**

The identification signs is next to the road to the property. The information meets the R645 Coal Rules.

**3. Topsoil**

All topsoil was used in reclamation.

**4.a Hydrologic Balance: Diversions**

Diversions were opened and would function as designed.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The reclaimed area is pocked for sediment control.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile has been reclaimed for several years. No inspection are required by the Division.

**8. Noncoal Waste**

The site is clear of non-coal waste material.

**10. Slides and Other Damage**

The road to Crandall Canyon is blocked off due to a rock slide causing a large tree to fall across the road. In addition to the tree a large boulder blocks the road. The permittee will contact a construction company to remove the material.

**12. Backfilling And Grading**

The total disturbed area is reclaimed and is backfilled and graded.

**18. Support Facilities, Utility Installations**

There are no facilities.



GARY R. HERBERT  
Governor

GREG BELL  
Lieutenant Governor

# State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

## Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

# Inspection Report

Permit Number: C0070004  
Inspection Type: PARTIAL  
Inspection Date: Thursday, July 14, 2011  
Start Date/Time: 7/14/2011 10:00:00 AM  
End Date/Time: 7/14/2011 2:00:00 PM  
Last Inspection: Wednesday, June 22, 2011

Inspector: Steve Demczak

Weather: Sunny, 80's

InspectionID Report Number: 2804

Accepted by: jhelfric

7/28/2011

Representatives Present During the Inspection:

Company Dennis Ware

OGM Steve Demczak

Permittee: **CASTLE GATE HOLDING CO**  
Operator: **CASTLE GATE HOLDING CO**  
Site: **CASTLE GATE MINE**  
Address: **PO BOX 30, HELPER UT 84526-0030**  
County: **CARBON**  
Permit Type: **PERMANENT COAL PROGRAM**  
Permit Status: **RECLAIMED**

### Current Acreages

7,619.00	<b>Total Permitted</b>
62.42	<b>Total Disturbed</b>
62.42	<b>Phase I</b>
58.10	<b>Phase II</b>
	<b>Phase III</b>

### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violatios were issued.

The Permittee notified the Division that the required first quarter of 2011 surface water monitoring information for the Castle Gate Mine was in the DOGM EDI pipeline and was acceptable for uploading. The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit. There are no other "special" permit conditions.

The field conditions in Sowbelly and Hardscrabble Canyons remain virtually unchanged, as does the condition of the reclaimed area for Adit #1.

Inspector's Signature:

Steve Demczak,

Inspector ID Number: 39

Date

Wednesday, July 13, 2011



Permit Number: C0070004  
 Inspection Type: PARTIAL  
 Inspection Date: Thursday, July 14, 2011

Inspection Continuation Sheet

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

Castle Gate is in the Phase II stage of reclamation. There are two sub-stations and a small area (Adit #1) that are in Phase I.

**2. Signs and Markers**

Identification signs are at the gates to the property.

**3. Topsoil**

All topsoil was used in reclamation.

**4.a Hydrologic Balance: Diversions**

All diversions were opened and would function as designed.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The reclaimed site is pocked for sediment control. The amount of vegetation on the site also reduces sediment movement. There are no signs of erosion to the sites.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

All refuse piles are reclaimed and no inspections are required.

**8. Noncoal Waste**

The site was clear of non-coal waste materials.

**10. Slides and Other Damage**

No slides or damage was noticed during the inspection.

**12. Backfilling And Grading**

The sites are completely reclaimed. All backfilled material was used.

**13. Revegetation**

This site in my judgment most areas are highly vegetated. The constance amount of rainfall has caused the vegetation to grow high.

**18. Support Facilities, Utility Installations**

There are no facilities at Castle Gate.