0022 RE 5-4-87 File

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Job ON



# inspection report

Permit No. ACT/007/007
Inspection Date 4/20/87

Permittee/Operator Name Kaiser Coal Corporation (KCC)
Business Address P.O. Box D
City Sunnyside State UT Zip 84539
Mine Sunnyside Complex ☐ Surface ☒ Underground ☐ Other
County Carbon State Utah
Company Official(s) Carl Winters
State Official(s) Jim Fricke
Time of inspection 12:30 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 3/25/87 Weather conditions Clear & Mild
Acreage 14,535 ☒ Permitted 287.4 ☒ Disturbed ☐ Regraded ☐ Seeded 287.4 ☒ Bonded
Enforcement Action None

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☒ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☐ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| a Stream channel diversions | ☐ | ☐ | ☐ | ☐ |
| b Diversions | ☐ | ☐ | ☐ | ☐ |
| c Sediment ponds and impoundments | ☐ | ☐ | ☐ | ☐ |
| d Other sediment control measures | ☐ | ☐ | ☐ | ☐ |
| e Surface and groundwater monitoring | ☒ | ☐ | ☐ | ☐ |
| f Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☐ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☐ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☒ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☐ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☐ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| a Construction | ☐ | ☐ | ☐ | ☐ |
| b Drainage controls | ☒ | ☐ | ☐ | ☒ |
| c Surfacing | ☒ | ☐ | ☐ | ☒ |
| d Maintenance | ☐ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☐ | ☐ | ☐ | ☐ |

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date _____

Please number comments to correspond with topics on previous page.

16b. Road culverts RC2-1, RC3-3, RC3-4, RC3-5 and RC3-6 were inspected for erosion control measures on the culvert outlets. These culverts are in compliance and are a portion of the culverts listed under permit stipulation UMC 817.47.

16c. The haul road from the prep plant to the coarse refuse pile was in good condition and had been watered for dust control. ~~in the morning~~

Copy of report mailed to D. Griffin (OSM) Carl Winters (KCC)

Copy of report given to J. Helfrich & J. Whitehead

Inspector's signature Jim Fricke No. 22

4/30/87

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE



an equal opportunity employer