



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangemer, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D.; Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: October 14, 1988
8:00 am - 9:30 am

Permittee and/or Operators Name: Kaiser Coal Corporation
Business Address: P.O. Box D Sunnyside, Utah 84539
Mine Name: Sunnyside Permit Number: ACT/007/007
Type of Mining Activity: Underground Surface Other
County: Carbon State: Utah
Company Official(s): Bill Balaz (KCC), Rick Fisher (Environmental Power)
State Official(s): Bill Warmack
Partial: Complete: Date of Last Inspection: October 6, 1988
Weather Conditions: Clear and cool
Acreage: Permitted 14475 Disturbed 310 Regraded Seeded Bonded 287
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	(X)
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION October 14, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

This partial inspection served as a follow-up to a NOV that was issued on October 6, 1988 by the undersigned inspector and to acquaint Rick Fisher of Environmental Power with the situation.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

1. The area below the topsoil borrow area and east of the east slurry pond was reviewed with Mr. Balaz and Mr. Fisher. Requirements for the pond and diversion ditch designs per the Division letter of August 23, 1988 were discussed.
2. The disturbed area in question is a part of Environmental Power's property which was acquired in a lease option with Kaiser Coal Corporation. Division approval to delete approximately 73 acres from Kaiser's property was granted on July 1, 1988. Hence, the aforementioned NOV has been written to incorporate Environmental Power.

4d. OTHER SEDIMENT CONTROL MEASURES:

Silt fences are being installed along the western refuse pile access road. For the most part, installation is complete, however, some final enhancement work needs to be accomplished to ensure structures will function properly.

7. COAL PROCESSING WASTE:

The southern outslope bank of the refuse pile will be graded to alleviate some of the associated maintenance work. Some consideration should be given towards decreasing the overall outslope angle or establishing some type of water traps (terraces, furrows, etc.). Repair work will commence when manpower and or funds are available to complete the project.

Copy of this Report:

Mailed to: Bill Balaz, KCC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: Oct. 14, 1988

William A. Warmack 10/14/88