

0031



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 15, 1988
12:00-3:00 p.m.

Permittee and/or Operators Name: Kaiser Coal Corporation
Business Address: P.O.Box D Sunnyside, Utah 84539
Mine Name: Sunnyside Permit Number: ACT/007/007
Type of Mining Activity: Underground Surface Other
County: Carbon State: Utah
Company Official(s): None
State Official(s): Bill Warmack and Bill Malencik
Partial: XX Complete: Date of Last Inspection: June 10, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 14475 Disturbed 310 Regraded Seeded Bonded 287
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	(X)
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	(X)
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION July 15, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Mine site conditions were dry; no visual evidence of previous precipitation. Maintenance items listed herein do not constitute a violation of the UMC standards and are listed only for preventive purposes.

1. PERMITS:

1. Certificate of insurance sent to DOGM on April 20, 1988.
2. Letter to John Whitehead of DOGM requesting an incidental boundary change near the base of coarse refuse pile to facilitate the cleaning of the culvert. Reclamation of the old CRT pond and newly disturbed area to be completed by November 1988.
3. Kaiser received an approval on July 1, 1988 to delete from their permit approximately 73 acres which Sunnyside Fuel Corporation recently leased.
4. Annual report was submitted on June 17, 1988.

2. SIGNS AND MARKERS:

The mine identification sign located near the main gate should be replaced before it becomes illegible.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

1. Inlet areas to the manshaft pond are in need of additional erosion protection.
2. Second quarter pond inspections were reviewed and found in good order.

4d. OTHER SEDIMENT CONTROL MEASURES:

Silt fence by upper substation is in need of repair although functional at this time.

7. COAL PROCESSING WASTE:

Refuse pile inspection was made on June 10, 1988.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION July 15, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

15. CESSATION OF OPERATIONS:

The operator was questioned as to whether or not mine has ceased operations, and he replied that the mine status is still idle.

Copy of this Report:

Mailed to: Bill Balaz, KCC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: July 27, 1988