



UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

0058

NO. N 88-26-11-1

To the following Permittee or Operator:

Name Kaiser Coal Corporation

Mine SUNNYSIDE Surface Underground Other

County CARBON State UTAH Telephone 888-4421

Mailing Address P.O. Box 2, SUNNYSIDE, UT 84539

State Permit No. ACT/007/007

Ownership Category State Federal Fee Mixed

Date of inspection April 27, 28 & 29, 1988, 19____

Time of inspection _____ a.m. p.m. to _____ a.m. p.m.

Operator Name (other than Permittee) NA

Mailing Address NA

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling April, 29, 1988 Time of service/mailling 11:30 a.m. p.m.

Barry Grosley
Permittee/Operator representative

Environmental Coordinator
Title

Barry Grosley
Signature

Reclam Specialist
Title

Wm. J. Malencik
Division of Oil, Gas & Mining representative

#26
Identification Number

Wm. J. Malencik
Signature 4/29/88

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 88-26-11-1

Violation No. 1 of 1

Nature of violation

Failure to provide and/or maintain sediment control measures

Provisions of act, regulations or permit violated

817.45(i)(iii) c, d, e, f

Portion of operation to which notice applies

- Number Two Canyon, lower end & below Belt line. This is the area where a water line burst recently. Also above culvert RC-10-4.
- Embankment On Train Roadcut
- Borrow Area East Of The East Slurry Pond.

Remedial action required (including any interim steps)

Provide protection and sediment control.

Abatement time (including interim steps)

- 90 Days On Number Two Canyon Incident 7-29-88
- 30 Days On Train Roadcut & Borrow Area. 5-28-88