

0018
SRS, Inc.

Sunnyside Reclamation & Salvage, Inc.
P.O. Box 99 — Sunnyside, Utah 84539

ACT/007/007 #2

RECEIVED
SEP 20 1989

September 18, 1989

DIVISION OF
OIL, GAS & MINING

Mr. Henry Sauer
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Henry:

Re: Topsoil Analysis Taken From Second
Mine Water Pond Construction Area

Please find enclosed the analysis of the topsoil taken from the Second Mine Water Pond construction area.

Three locations were used at twelve-inch depths. The first six inches (0-6) are represented by 1a, 2a, and 3a. The remaining six inches (6-12) are represented by 1b, 2b, and 3b.

If you have any questions, please feel free to call.

Sincerely,



Karl R. Houskeeper
Environmental Coordinator

KRH:th

cc: Bill Balaz

Enclosures

* Note:

Inset into Appendix T-1

RVS