0017

RUS

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No ACT/007/007

Inspection Date Sept. 19, 1989

Permittee/Operator Name SUNNYSIDE RECLAMATION & SALVAGE, INC.

Business Address P.O. Box 99

City SUNNYSIDE State UT Zip 84539

Mine SUNNYSIDE ☐ Surface ☒ Underground ☐ Other

County CARBON State UT

Company Official(s) KARL HOUSKEEPER

State Official(s) BILL WAKMACK, LYNN KUNZLER

Time of inspection 10:30 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection AUG 22, 1989 Weather conditions WARM

Acreage ☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☒	☐	☐	☒
c Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date Sept. 19, 1989

Please number comments to correspond with topics on previous page.

GENERAL: A PORTION OF THIS INSPECTION WAS CONDUCTED IN PART WITH MR. LARRY DALTON (DWR) TO ASSESS THE CONDITION OF GLASSY TRAIL CREEK. MS LYNN KUNZEL, BIOLOGIST FOR THE DIVISION, WAS ALSO PRESENT.

4c. SEDIMENT PONDS: CONSTRUCTION OF THE NEW MINE DISCHARGE POND IS UNDERWAY. VEGETATION HAS BEEN REMOVED & TOPSOIL HAS BEEN SALVAGED. UPON COMPLETION OF THE TOPSOIL PILE, IT WILL BE SEEDED & SIGNED.

4d. OTHER SEDIMENT CONTROLS: SILT FENCES AT THE FOLLOWING AREAS HAVE BEEN RE-INSTALLED OR AUGMENTED: 1) TWIN SHAFTS, 2) WHITMORE POND, 3) EAST OF MANSHAFT POND, 4) #8 CANYON, 5) OUTCROP FAN, 6) SSSF POND.

Copy of report mailed to

Copy of report given to

Inspector's signature UAW 9/19/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/007

Inspection Date Sept. 19, 1989

Please number comments to correspond with topics on previous page.

9. PROTECTION OF ENVIRONMENT: AS STATED ABOVE, MR. LARRY DALTON (DWR) WAS PRESENT TO ASCERTAIN WHETHER OR NOT ANY FURTHER CLEANUP MEASURES ARE REQUIRED FOR GRASSY TRAIL CREEK. CONCERNS ARE IN REGARDS TO THE EMULSION OIL & SLUDGE THAT WAS INADVERTENTLY DUMPED INTO THE CREEK BACK IN MARCH & APRIL. MR. DALTON WILL SEND HIS RECOMMENDATIONS TO THE SALT LAKE OFFICE.

16b. ROAD DRAINAGE: TWO ACCESS ROADS, WATER CANYON & BITCKOP FAN, HAVE BEEN REGRADED TO ENSURE PROPER DRAINAGES. BERMS HAVE BEEN INCREASED WHERE APPLICABLE.

16d. ROAD MAINTENANCE: THE REFUSE ROAD WAS PROPERLY TREATED, DUST WAS NOT EVIDENT.

Copy of report mailed to SLC FOR: JOE HELFRICH, BRIAN SMITH, KARL HOUSKEEPER (GES)

Copy of report given to PFO

Inspector's signature William A. Warnock 9/19/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049