

0028

SRS, Inc.

Sunnyside Reclamation & Salvage, Inc.

P.O. Box 99 — Sunnyside, Utah 84539

ACT/007/002
File #2+
#5

April 27, 1990

RECEIVED
APR 30 1990

DIVISION OF
OIL, GAS & MINING

Mr. Tom Monson
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Tom:

Re: Baseline Sampling For 002B Mine Water Discharge Pond

As indicated in my letter dated December 12, 1989 (see enclosure), SRS has collected four baseline samples from the 002B Mine Water Discharge Pond.

Two lab analysis have been received and are enclosed for your review. The remaining baseline analysis will be forwarded to you upon receipt.

SRS requests that you review the enclosed analysis and that the sampling parameters for the 002B Mine Water Discharge Pond be changed to operational parameters. No significant change in baseline results is expected from the remaining lab results.

If you have any questions, please feel free to call me.

Sincerely,



Karl R. Houskeeper
Environmental Coordinator

KRH:th

Enclosures

cc: Bill Balaz