



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial x Complete: Exploration:
Inspection Date & Time: 10/31/94 10:00 AM 12:00 Noon
Date of Last Inspection: 10/30/94

Mine Name: Sunnyside Coal Mine County: Carbon Permit Number: ACT/007/007
Permittee and/or Operator's Name: Sunnyside Coal Co.
Business Address: P.O. Box 99, Sunnyside, Ut 84529
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Scott Milovich Company Official(s): Darrel Leonard Federal Official(s): None
Weather Conditions: Cool
Existing Acreage: Permitted- 14475 Disturbed- 310 Regraded- 0 Seeded- 0 Bonded- 310
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.



## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/018

DATE OF INSPECTION: 10/31/94

(Comments are Numbered to Correspond with Topics Listed Above)

Note: During this inspection an "auction company" was moving equipment and organizing materials on the site for an upcoming auction.

4. Hydrologic Balance

a. Diversions-

Diversions and culverts observed during the inspection were generally in good repair and appeared to be functioning properly.

This inspector examined work done by the operator as abatement of NOV 94-32-2-2.

All berm, ditch and silt fence repair has been completed as required. The only remaining abatement step remaining is part 1 of 2 is seeding and rill repair. The operator has contracted that work out; the contractor was on site to examine the area and is scheduled to complete the work this week 10/31-11/4/94.

Part 2 of 2, pond certification was also completed. This inspector examined the report and the operator indicated that he would submit it to the Division.

I have recommended to the issuing inspector that the NOV be terminated.

Copy of this Report:

Mailed to: Darrell Leonard (SSC), Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:  \_\_\_\_\_ Scott Milovich #45 Date: 11/01/94