



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

gh

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340
(801) 359-3940 (Fax)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 4/24/98
Date of Last Inspection: 5/8/97

Mine Name: Sunnyside Mine County: Carbon Permit Number: FOR/007/007
Permittee and/or Operator's Name: Ken Rushton, Trustee
Business Address: 99 West Main, P.O. Box 212, Lehi, Utah 84043
Type of Mining Activity: Underground Surface Prep. Plant Other XXX
Company Official(s):
State Officials(s): Peter Hess Federal Official(s):
Weather Conditions: Warm, 50's
Existing Acreage: Permitted- 14475 Disturbed- 310 Regraded- Seeded- Bonded- 310
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ XXX Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, TOPSOIL, HYDROLOGIC BALANCE, EXPLOSIVES, DISPOSAL OF EXCESS SPOIL, etc.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: FOR/007/007

DATE OF INSPECTION: 4/24/98

(Comments are Numbered to Correspond with Topics Listed Above)

8. NONCOAL WASTE

A large amount of this type of material remains at the site, scattered throughout. A good deal of improvement can be made in a very short time upon initiation of reclamation.

10. SLIDES AND OTHER DAMAGE

Pilfering continues at the site. All of the windows in the remaining buildings have been broken out. The metal sheeting on the outside of the back warehouse annex has been stolen.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Ken Rushton, Trustee Marcia Petta (OSM)
Given to: Joe Helfrich (DOG M) Filed to: Price Field Office
Date: April 29, 1998

Inspector's Signature:  #46
Peter Hess