

0001



UTAH NATURAL RESOURCES Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/007/009

Inspection Date 12-17-86

Permittee/Operator Name Sunedco Coal Company

Business Address 7401 west Mansfield Ave., Suite 418 P.O. Box 35B

City Lakewood State Colo. Zip 80235

Mine Sage Point - Dugout Surface Underground Other

County Carbon State Utah

Company Official(s) None

State Official(s) Holland Shepherd, Rick Summers, Henry Austin (OSM)

Time of inspection 11:00 a.m. p.m. to 12:00 a.m. p.m. Partial Complete

Date of last inspection 9-11-86 Weather conditions Clear - Cool

Acreage 4475 Permitted Disturbed Regraded Seeded Bonded 70

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
- Stream channel diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
- Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	14. Subsidence control	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
- Sediment ponds and impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
- Other sediment control measures	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Construction	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

WHITE-DOG M YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

Inspection Report
Page 2

Permit Number: INA/007/009

Inspection date: 12-17-86

Comments

General Comments:

Nothing has changed at the site since the last inspection. All environmental impacts onsite are pre-SMCRA. The inspectors accessed the site via BLM maintained roads. The road which goes to Dugout Canyon was accessible, where as, the road which accesses the Fish Creek Canyon area was not because of the snow.

Mr. Tom Paluso, of Soldier Creek, mentioned that the operator was planning to discontinue the right-of-way agreement made with the BLM for an indefinite period of time. Also, according to information from Division personnel, the operator is planning to withdraw the lease agreements made between the federal land owner and the operator until a more opportune time.

Copy of this Report:

Mailed to: Charles Durrett, Donna Griffin, Tom Paluso (Soldier Creek Coal)

Given to: Sue Linner, Joe Helfrich, Rick Summers

Inspector's signature and number: Holler Shepherd 12-31-86