0003

File

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Soldier Creek Coal Company
Business Address: P.O. Box I, Price, Ut 84501
Mine Name: Save Point - Dugout Canyon Permit Number: PR0/007/009
Type of Mining Activity: Underground ✓ Surface ___ Other ___
County: Carbon
Company Official(s): none
State Official(s): Holland Shepherd
Inspection Date and Time: 9-11-86 2:30 - 4:30
Partial: ___ Complete: ✓ Date of Last Inspection: 6-30-86
Weather Conditions: Sunny - cool
Acreage: Permitted 4475.0 Disturbed 0.0 Regraded 0.0 Seeded 0.0 Bonded 70.0
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS	✓			
2. SIGNS AND MARKERS			✓	
3. TOPSOIL			✓	
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS			✓	
b. DIVERSION'S			✓	
c. SEDIMENT PONDS AND IMPOUNDMENTS			✓	
d. OTHER SEDIMENT CONTROL MEASURES			✓	
e. SURFACE AND GROUNDWATER MONITORING			✓	
f. EFFLUENT LIMITATIONS			✓	
5. EXPLOSIVES			✓	
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL			✓	
7. COAL PROCESSING WASTE			✓	
8. NONCOAL WASTE			✓	
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES			✓	
10. SLIDES AND OTHER DAMAGE			✓	
11. CONTEMPORANEOUS RECLAMATION			✓	
12. BACKFILLING AND GRADING			✓	
13. REVEGETATION			✓	
14. SUBSIDENCE CONTROL			✓	
15. CESSATION OF OPERATIONS			✓	
16. ROADS			✓	
a. CONSTRUCTION			✓	
b. DRAINAGE CONTROLS			✓	
d. SURFACING			✓	
e. MAINTENANCE			✓	
17. OTHER TRANSPORTATION FACILITIES			✓	
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS			✓	

INSPECTION REPORT
(Page 2)

Permit Number: PRO/007/009

Date of Inspection: 9-11-86

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments:

No post-SMCRA disturbance is evident at the site. The operator has indicated that there will be no mining activity at the Gauge Point - Dugout sites for several years to come.

Copy of this Report:
Mailed to: Dave Spillman, Donna Griffin
Given to: Joe Helfrich, Sue Linnell

Inspectors Signature and Number: Hilton Shepherd #9 9-12-86

0365Q 1-2