



3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 85-6-15-1

notice of violation

To the following Permittee or Operator:

Name U.S. Fuel Company

Mine Hiawatha Complex Surface Underground Other

County Carbon State UTAH Telephone 801-343-2471

Mailing Address Hiawatha UT 841527

State Permit No. ACT/007/011

Ownership Category State Federal Fee Mixed

Date of inspection Dec. 4, 1985, 19 85

Time of inspection 1:30 a.m. p.m. to 4:00 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Due to lateness of the day and request of operator not to stay late Nov was issued from office following a telephone communication at 2:30 PM 12/5/85.

Date of service/ mailing Dec 5, 1985 Time of service/ mailing 3 a.m. p.m.

Jean Semborski
Permittee/Operator representative

Engineering Dept.
Title

Mailed from office
Signature 30K

Barton O. Kale
Division of Oil, Gas & Mining representative

Mining Field Specialist
Title

Barton O. Kale
Signature

#6
Identification Number

SEE REVERSE SIDE
WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

DOG M 603



NOTICE OF VIOLATION NO. N 85-6-15-1

Violation No. 1 of 1

Nature of violation
Failure to maintain disturbed area culverts and
ditches to design criteria for volume of flow-
Failure to maintain inlets to sediment pond to convey
flow as designed

Provisions of act, regulations or permit violated
UMC 817. 43 (c)
817. 45 (i)

Portion of operation to which notice applies
Disturbed area culverts to the sediment ponds at
both the Middle Fork and South Fork Mine yards.
Inlets to sediment ponds at both locations

Remedial action required (including any interim steps)
Clear all disturbed culverts of all obstructions to convey
the designed flow to the appropriate sediment ponds.
This includes removing snow, restoring the appropriate
gradient and volume for runoff.

Abatement time (including interim steps)
~~1~~ - Dec 12, 1985 -