



UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

0025

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

Page 1 of 3

✓  
Feb 10/9/87

NO. N 87-9-10-2

notice of violation

To the following Permittee or Operator:

Name U.S. Fuel Company

Mine Hiawatha Complex  Surface  Underground  Other

County Carbon State Utah Telephone 637-2253

Mailing Address Hiawatha, Utah, 84527

State Permit No. ACT/007/011

Ownership Category  State  Federal  Fee  Mixed

Date of inspection 9-~~22~~ 24, 25 & 29 - 87, 1987

Time of inspection 9:00  a.m.  p.m. to 11:00  a.m.  p.m.

Operator Name (other than Permittee) same as above

Mailing Address same as above

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling 9-29-87 Time of service/mailling 11:00  a.m.  p.m.

Jean Semberoski  
Permittee/Operator representative

Mine Engineer  
Title

Jean Semberoski  
Signature

Holland Shepherd  
Division of Oil, Gas & Mining representative

Reclamation Specialist  
Title

Holland Shepherd  
Signature

#9  
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

925 /



### NOTICE OF VIOLATION NO. N 87-1-10-2

Violation No. 1 of 2

Nature of violation

Failure to notify the Division within 5 days after receiving the results indicating an NPDES permit effluent limitation noncompliance had occurred.

Provisions of act, regulations or permit violated

UMC 817.52 (b)(1)(ii)

Portion of operation to which notice applies

The operator received analysis from the Midland portal discharge point 001, which indicated a TDS level of 748 mg/l. The permit limits TDS to 720 mg/l. The analysis was received on 7-17-87.

Remedial action required (including any interim steps)

1. Make the appropriate notification to the regulatory agencies.

Abatement time (including interim steps)

1. by 10-9-87



### NOTICE OF VIOLATION NO. N 87-9-10-2

Violation No. 2 of 2

Nature of violation

Failure to divert runoff using protected channels or pipes through disturbed areas so as not to cause additional erosion.

Provisions of act, regulations or permit violated

UMC 817.45 (iii) (e)

Portion of operation to which notice applies

The east end of the Middle Fork, upper yard and parking facility. Specifically the hillside between the tipple yard and the parking lot, and the drainage diversions supporting this area.

Remedial action required (including any interim steps)

1. Stabilize large gully on hillside by best practicable method
2. Improve berm on the east end of the north drop drain, located at the end of the conveyor.
3. If gully to be used as a diversion, ~~submit plans for~~ and ~~approval to use it as such~~ amend plan accordingly.

Abatement time (including interim steps)

Items #1 through #3 by Oct. 30, 1987