9-19-89

7090

0011

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

RECEIVED
SEP 15 1989
DIVISION OF
OIL, GAS & MINING

Gd Sue SL

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: September 7, 1989
2:00 p.m. - 4:00 p.m.

Permittee and/or Operators Name: U.S. Fuel Company
Business Address: Hiawatha, Utah 84527
Mine Name: Hiawatha Complex Permit Number: ACT/007/011
Type of Mining Activity: Underground XX Surface ____ Other _____
County: Carbon State: Utah
Company Official(s): Jean Semborski
State Official(s): Daron Haddock
Partial: XX Complete: _____ Date of Last Inspection: August 9-10, 1989
Weather Conditions: Mostly sunny, windy
Acreage: Permitted 12,249 Disturbed 278.7 Regraded _____ Seeded _____ Bonded 313.5
Enforcement Action: NOV # N89-28-7-1 modified

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	( )	( )	(X)
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	( )	( )	(X)

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: ACT/007/011 DATE OF INSPECTION Sept. 7, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

4b. DIVERSIONS:

The diversions around the preperation plant appear to be working correctly. The ditch along the tracks has recently been cleaned.

6. DEVELOPMENT WASTE AND SPOIL DISPOSAL:

The area cited in NOV N89-28-7-1 was inspected. Most of the spoil material which had been dumped at the parking lot of King #4 Mine had been cleaned up. However, some material had been left on the slope. The operator requested more time to enable them to get the proper equipment to do the clean up. The NOV was modified to allow for the extra time needed. The abatement date is now September 22, 1989.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS:

On September 5, 1989, the operator received approval to replace a portion of the Mohrland pipeline. Approximately 1200 - 1500 feet of pipeline will be replaced just above the Mohrland loadout. This section of pipeline has been recently plagued with leaks and the replacement of the pipe should be a big improvement. Work on the pipeline replacement is proceeding at the present time.

Copy of this Report:
Mailed to: Jean Semborski, U.S. Fuel
Mailed to SLC for: Brian Smith, OSM; Joe Helfrich
Filed to: PFO

Daron R. Haddock

Inspectors Signature and Number: Daron R. Haddock #28 Date: Sept. 12, 1989