

2-27-89 7090

2811



0023

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

notice of violation

NO. N 89-28-2-1

To the following Permittee or Operator:

Name U.S. Fuel

Mine Hiawatha Complex Surface Underground Other

County Carbon State Utah Telephone 343-2471

Mailing Address Hiawatha, Utah 84527

State Permit No. ACT/007/011

Ownership Category State Federal Fee Mixed

Date of inspection Feb 17, 1989, 19__

Time of inspection 9:00 a.m. p.m. to 4:00 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Feb 22, 1989 Time of service/ mailing 12:15 a.m. p.m.

Jean Semborski
Permittee/Operator representative

Environmental Coordinator
Title

Jean Semborski
Signature

Daron R. Haddock
Division of Oil, Gas & Mining representative

Reclamation Specialist
Title

Daron R. Haddock
Signature

#28
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 89-28-2-1

Violation No. 1 of 1

Nature of violation

f Failure to maintain a support facility in a manner which, 1) prevents additional contributions of suspended solids to runoff or stream flow outside the permit area and 2) minimizes erosion to the extent possible

Provisions of act, regulations or permit violated

UMC 817,181

UMC 817,45 (i) and (iii)

Portion of operation to which notice applies

Water pipeline which supplies water to the Hiawatha area from Mohrland. A Break in the pipe approximately 1/2 mile prior to the water tanks and the affected area in the proximity of the break.

Remedial action required (including any interim steps)

- 1) Repair break in pipeline as expeditiously as weather conditions will allow
- 2) Install sediment control (ie: silt fence, straw bales or other) to treat run off and drainage from the area of the break.

Abatement time (including interim steps)

1) March 24th, 1989 by 5:00 PM

2) March 1st, 1989 by 5:00 PM