

0015



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John
02 7

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

PERMIT NO.: ACT/007/011 Inspection Date: July 30, 1991
 Permittee and/or Operators Name: Hiawatha
 Business Address: P.O. Box A
 City: Hiawatha State: Utah Zip: 84527
 Mine Name: Hiawatha Complex
 County: Carbon State: Utah
 Type of Mining Activity: Underground Surface Other
 Company Official (s): Bob Eccli
 State Officials (s): Stephen J. Demczak
 Time of Inspection: 8:00 a.m. p.m. to 11:30 a.m. p.m.
 Partial Complete: Date of Last Inspection: June 19, 1991
 Weather Conditions: Warm, High 80's
 Acreage: Permitted 20,700 Disturbed 290 Regraded Seeded
 Bonded 290 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/011 INSPECTION DATE July 30, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil -

The topsoil piles were inspected showing no signs of wind or water erosion. Vegetation is growing on top of the piles. The berms were intact, and they were also cleaned out recently.

4c. Sediment Ponds and Impoundments -

Some of the ponds had small amounts of water, but no ponds were discharging at the time of inspection. No erosion was present on slopes of ponds.

Copy of report:

Mailed to: Hiawatha (Bob Eccli)

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39

Date: 8/2/91 