



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

MDZ
Qpd

RECEIVED

MAR 28 1991

DIVISION OF OIL GAS & MINING

INSPECTION REPORT

PERMIT NO.: ACT/007/011
Inspection Date: March 25, 1991

Permittee and/or Operators Name: U.S. Fuel Company
Business Address: P.O. Box A
City: Hiawatha State: Utah Zip: 84527
Mine Name: Hiawatha Complex County: Carbon State: Utah
Type of Mining Activity: Underground XX Surface Other
Company Official (s): _____
State Officials (s): Stephen J. Demczak DOGM
Time of Inspection: 9:00 (X)a.m. () p.m. to 12:30 () a.m. (X) p.m.
Partial XX Complete: _____ Date of Last Inspection: 2/13-15/91
Weather Conditions: Cool/Clear
Acreage: Permitted 20,700 Disturbed 290 Regraded _____ Seeded _____
Bonded 290 Enforcement Action: Yes

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(X)	()	()	(X)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/011 INSPECTION DATE March 25, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. Diversions:

Checked several diversions related to NOV 91-39-1-2 and the work was adequately performed. The only outstanding portion to the violation is the clear water diversion at Southfork. The NOV was extended due to snow to finish this violation.

c. Sediment Ponds and Impoundments:

The violation 3 of part 4 was terminated because the work performed complied with R614-301-742.221.34. The violation 1 of part 4 is presently under Division review.

8. NONCOAL WASTE:

A NOV 91-39-3-1 was written for noncoal waste throughout the #4 and #5 mine pad areas. The five gallon oil containers were located (a) along the road between #4 & 5 mine (b) along red warehouse (c) next battery charging station (d) by outside belt drive and (e) next to fuel station (diesel storage).

Copy of report:

Mailed to: Bob Eccli (USFC)

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39 Date: 3/25/91

