



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/007/011 Inspection Date: September 18, 1992
 Permittee and/or Operators Name: U.S. Fuel
 Business Address: P.O. Box A City: Hiawatha State: UT Zip: 84527
 Mine Name: Hiawatha Complex County: Carbon State: UT
 Type of Mining Activity: Underground XX Surface Other
 Company Officials: Mike Watson State Officials: Stephen J. Demczak
 Time of Inspection: 9:00 a.m. - 2:00 p.m. Partial X Complete:
 Acreage: Permitted 20700 Disturbed 290 Regraded 0
 Seeded 0 Bonded 290 Date Last Inspected: August 20, 1992
 Weather Conditions: Warm 70's Enforcement Action: None

CATEGORIES

	YES	NO	N/A	NOTES
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	(X)
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()
19. AVS Check	()	()	()	()

Permit No. ACT/007/011 Inspection Date September 18, 1992(Comments are Numbered to Correspond with Topics Listed Above)3. Topsoil -

The topsoil piles were inspected with plant growth on the piles and no evidence of cattle grazing on the piles. In the spring and fall cattle are herd by ranchers down the road, which make topsoil piles easily accessible for cattle to graze upon.

4b. Diversion -

The rehabilitation of the diversion ditch along Middle Fork road has been completed with check dams installed to slow down storm water and prevent further erosion, and commence silting of the ditch to restore proper ditch design.

11. Contemporaneous Reclamation -

The dismantling of the Prep Plant is approximately 50% completed. The bonding for the plant is just under one-half of a million dollars. The demolition of the plant should be finished this year. U. S. Fuel Company has commenced contemporaneous reclamation on the #4 refuse pile which is located on the west side of the main highway to Hiawatha. The pile is being regraded and contoured and will be examined by the Division before approval will be given to place topsoil on the pile.

Copy of report:

Mailed to: U.S. Fuel Co.Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: October 7, 1992Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak