



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gh

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: X Complete: Exploration:
Inspection Date & Time: 6/15/94 9:30AM-12:00Noon
Date of Last Inspection: 5/17/94

Mine Name: Wellington Prep Plant County: Carbon Permit Number: ACT/007/012
Permittee and/or Operator's Name: Castle Valley Resources
Business Address: P.O. Box 1282, Huntington, UT 84528
Type of Mining Activity: Underground Surface Prep. Plant X Other
State Officials(s): Scott Milovich, Steven Demczak, Pete Hess Company Official(s): Jesse Alcon, Todd Welty
Federal Official(s): None Weather Conditions: Clear
Existing Acreage: Permitted- 1720 Disturbed- 256 Regraded- 1.5 Seeded- 1.5 Bonded- 744
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June)_(date); AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 6/15/94

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers-

New identification signs have been placed at all entrances to the property.

3. Topsoil-

Topsoil storage areas were properly identified and a berm containing the pile was in place around all of them.

4. Hydrologic Balance-

a. Diversions: All diversions that were inspected appeared to be functioning properly.

b. Sediment Ponds and Impoundments: None of the ponds were discharging at the time of the inspection. There were no signs of erosion at the inlets, outlets, or embankments.

The new Dryer pond was under construction. During the inspection it was not apparent whether or not an emergency spillway was being installed. The approved amendment regarding the pond, #92B, indicates that an emergency spillway is to be constructed.


8. Non Coal Waste-

The containment berm around the fuel storage tanks was in need of maintenance. The operator agreed to shore-up the berm and to keep the fuel hose inside of the berm.

Copy of this Report:

Mailed to: Castle Valley Resources, Jay Marshall, Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:  Scott Milovich #45 Date: 6/17/94