



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangarter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

Partial: XX Complete: Exploration

Inspection Date/Time: January 7, 1994/09:30am-02:00pm

Date of Last Inspection: December 13, 1993

Mine Name: Wellington Prep Plant County: Carbon Permit Number: ACT/007/012  
 Permittee and/or Operator's Name: Castle Valley Resources  
 Business Address: P. O. Box 1282, Huntington, UT 84528  
 Type of Mining Activity: Underground Surface Prep XX Other  
 Officials(s): State: Stephen J. Demczak Company: Larry Johnson  
 Federal Official(s): \_\_\_\_\_ Weather Conditions: Cool, 20's  
 Existing Acreage: Permitted-1720 Disturbed-356 Regraded-1.5 Seeded-1.5 Bonded-744  
 Increased/Decreased: Permitted- \_\_\_\_\_ Disturbed- \_\_\_\_\_ Regraded- \_\_\_\_\_ Seeded- \_\_\_\_\_ Bonded- \_\_\_\_\_  
 Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture  
 Reclamation ( Phase I/ Phase II/ Final Bond Release/ Liability \_\_\_\_\_ Year)

## REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<u>[XX]</u>	<u>[ ]</u>	<u>[XX]</u>	<u>[ ]</u>
2. SIGNS AND MARKERS	<u>[XX]</u>	<u>[ ]</u>	<u>[XX]</u>	<u>[ ]</u>
3. TOPSOIL	<u>[XX]</u>	<u>[ ]</u>	<u>[XX]</u>	<u>[ ]</u>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<u>[XX]</u>	<u>[ ]</u>	<u>[XX]</u>	<u>[ ]</u>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<u>[XX]</u>	<u>[ ]</u>	<u>[XX]</u>	<u>[ ]</u>
c. OTHER SEDIMENT CONTROL MEASURES	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
d. WATER MONITORING	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
e. EFFLUENT LIMITATIONS	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
5. EXPLOSIVES	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
8. NONCOAL WASTE	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
10. SLIDES AND OTHER DAMAGE	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
11. CONTEMPORANEOUS RECLAMATION	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
12. BACKFILLING AND GRADING	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
13. REVEGETATION	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
14. SUBSIDENCE CONTROL	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
15. CESSATION OF OPERATIONS	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
b. DRAINAGE CONTROLS	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
17. OTHER TRANSPORTATION FACILITIES	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
19. AVS CHECK (4th Quarter-April, May, June) _____ date	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
20. AIR QUALITY PERMIT	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>
21. BONDING & INSURANCE	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>	<u>[ ]</u>

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: January 7, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The mine permit stipulation is being reviewed by the Division. This submittal by the operator is in response to a Division Order. A preliminary discussion of the submittal is that it may be less in compliance than the initial submittal.

2. Signs and Markers -

The identification signs have not changed. The Division is in the process of reviewing a permit transfer of the property to NIECO.

3. Topsoil -

The topsoil piles have berm surrounding them to contain the topsoil. There were no signs of erosion on the piles.

4a. Diversions -

The diversions were stable and no signs of erosion were seen. The diversions have not flowed water since fall.

4b. Sediment Pond and Impoundments -

The ponds were not discharging at the time of inspection. There were no signs of erosion to inlets, outlets, or embankments. The sediment ponds by rail loadout did contain a small amount of water.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Castle Valley Resources

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: January 11, 1994

Inspector's Signature and Number:

  
Stephen J. Demczak

#39