



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Role, Name. Row 1: OGM, Joe Helfrich, Environmental Scientist III. Row 2: Company, Mark Reynolds, Resident Agent.

Inspection Report

Table with 2 columns: Field, Value. Fields include Permit Number (C0070011), Inspection Type (COMPLETE), Inspection Date (Monday, June 26, 2006), Start Date/Time (6/26/2006 10:30:00 AM), End Date/Time (6/26/2006 1:30:00 PM), Last Inspection (Tuesday, May 30, 2006).

Inspector: Joe Helfrich, Environmental Scientist III

Weather: windy raining 75

InspectionID Report Number: 1005

Accepted by: whedberg
7/10/2006

Permitee: HIAWATHA COAL CO INC
Operator: HIAWATHA COAL CO INC
Site: HIAWATHA MINE COMPLEX
Address: PO BOX 1245, HUNTINGTON UT 84528
County: CARBON
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Rows: 12,177.00 Total Permitted, 290.00 Total Disturbed, Phase I, Phase II, Phase III.

Mineral Ownership

- Checked: Federal, State, Fee. Unchecked: County, Other.

Types of Operations

- Checked: Underground. Unchecked: Surface, Loadout, Processing, Reprocessing.

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a complete inspection of the Hiawatha complex. There are no amendments pending.

Inspector's Signature: _____ Date: Monday, July 10, 2006

Joe Helfrich, Environmental Scientist III
Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit was issued on March 14, 2002 and expires on March 14, 2007. Other documents include the following:

- Certificate of Insurance by Scottsdale Insurance Co. Policy # CLS0668789 effective 01/27/2004 and expires 1/27/2006.
- UPDES Permit UT-0023094 issued 10/01/2004 and expires 09/30/2009 at midnight.
- Air Quality Permit BAQE-502-89 issued 07/25/1989 and remains in effect.
- Bond is an irrevocable letter of credit issued by Bank One in the amount of \$2,838,000.

2. Signs and Markers

Signs containing the required information were posted at points of access to the mining facilities. At the time of this inspection, all points of access to the Hiawatha complex were open.

4.a Hydrologic Balance: Diversions

Recent Spring snowmelt has resulted in the deposition of rocks in the diversions along the access roads to the King 4, 5, and 6 locations. The rocks are not impeding the flow in the diversions but should be removed by this Fall.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Quarterly inspections of the sediment ponds were conducted on 5/31/2006. All ponds were noted as being stable with no cracks or signs of structural weakness.

4.d Hydrologic Balance: Water Monitoring

Hard copies of the quarterly DMR's, (first quarter 2006), were available for inspection for sites D001 and D002.

4.e Hydrologic Balance: Effluent Limitations

The DMR data was in compliance with the coal rules.

7. Coal Mine Waste, Refuse Piles, Impoundments

The current refuse pile and slurry pond inspections were completed on June 20 and 21, 2006. The ponds were also in good repair and showed no signs of structural weakness or hazards.

15. Cessation of Operations

The loading of slurry fines from the #1 slurry pond is the only ongoing mining activity at the Hiawatha complex. The company plans to increase the removal of fines during the next month.

Permit Number: C0070011
Inspection Type: COMPLETE
Inspection Date: Monday, June 26, 2006

16.a Roads: Construction, Maintenance, Surfacing

The access road from Slurry pond #1 to the railroad tracks should be watered occasionally unless it would create a traction problem.

21. Bonding and Insurance

The bond is an irrevocable letter of credit issued by Bank One in the amount of \$2,838,000. The insurance is current through 1/27/2007. A copy of the Insurance was available for inspection at the office located in Hiawatha.