

notice of violation

NO. N 87-17-5-1

To the following Permittee or Operator:

Name Kaiser Coal Company

Mine Wellington Prep Plant Surface Underground Other

County Carbon State UT Telephone 888-4721

Mailing Address PO Box 0, Sunnyside, UT 84539

State Permit No. ACT/007/012

Ownership Category State Federal Fee Mixed

Date of inspection November 16-17, 1987, 19

Time of inspection 2:30 P. (11/16) a.m. p.m. to 4:00 P. (11/16) a.m. p.m.
7:30 A. (11/17) a.m. p.m. to 11:15 AM (11/17) a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling November 17, 1987

Time of service/mailling 11:15 a.m. p.m.

Barry Groseley
Permittee/Operator representative

Mining Engineer
Title

Barry Groseley
Signature

Lynn Kunzler
Division of Oil, Gas & Mining representative

Reclamation Biologist
Title

[Signature]
Signature

#17
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

1704



NOTICE OF VIOLATION NO. N87-17-51

Violation No. 1 of 1

Nature of violation

Failure to pass disturbed area runoff through treatment facility before leaving the permit area and failure to maintain sediment control structures

Provisions of act, regulations or permit violated

UMC 817, 42(a) (1) & (2)
UMC 817, 45

Portion of operation to which notice applies

a point approx. 750 feet west of the gate along the slurry pipeline corridor.

Remedial action required (including any interim steps)

- 1). Repair berm along slurry pipeline corridor
- 2). Repair gully in slurry pipeline corridor fill.
- 3). install silt fence or strawbale dike where runoff leaves the borrow area at the base of the fill.

Abatement time (including interim steps)

Install silt fence or strawbale dike within 2 weeks (by Dec. 1, 1987)
Repair berm and gully within 30 days (by Dec. 17, 1987)