

Document Information Form

Mine Number: C/007/012

File Name: Internal

To: DOGM

From:

Person N/A

Company OFFICE OF SURFACE MINING RECLAMATION AND ENFORCEMENT

Date Sent: N/A

Explanation:

TEN-DAY NOTICE

cc:

File in:
C/ _____, _____, Internal

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office: Albuquerque FO
625 Silver SW Suite 310
Albuquerque, NM 87102
Telephone Number: 505-766-1484

007/012

Number: X - 88 - 02 - 107 - 3 TV 5

Ten-Day Notice to the State of Utch, Division of Oil, Gas and Mining

You are notified that, as a result of a Federal inspection (4/26-27/88) (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: <u>Kaiser Coal, Inc.</u> <small>(Or Operator if No Permit)</small>	County: <u>Carbon</u>	<input checked="" type="checkbox"/> Surface
Mailing Address: <u>P.O. Box 10, Swanyside, Utah 84539</u>		<input type="checkbox"/> Underground
Permit Number: <u>007/012</u>	Mine Name: <u>Wellington Preparation Plant</u>	<input checked="" type="checkbox"/> Other <u>Plant</u>

NATURE OF VIOLATION AND LOCATION: Failure to protect side slopes of impoundments against erosion; west bank of the Auxiliary Pond

Section of State Law, Regulation or Permit Condition believed to have been violated: UMC 817.49(c)

NATURE OF VIOLATION AND LOCATION: Failure to divert surface drainage from the area above the coal processing waste pile, failure to divert surface runoff from the crest and face of the coal processing waste pile; The course

Coal Processing Waste Retain Pile East side of lower coal slurry pile
Section of State Law, Regulation or Permit UMC 817.83
Condition believed to have been violated: UMC 817.12(c)

NATURE OF VIOLATION AND LOCATION: Failure to provide for an appropriate combination of principal and emergency spillways at the Slurry Line Sediment Pond

Section of State Law, Regulation or Permit UMC 817.46(c)
Condition believed to have been violated:

Remarks or Recommendations: MAY 2

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No. _____ Date _____
In C/ _____ Internal _____
For additional information _____

Date of Notice: 4-27-88
Sent Certified on 4-27-88
Cert. Rec. # 121 613 527

DIVISION OIL, GAS & I
Signature of Au _____
Print Name and _____

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE

Originating Office: Albuquerque FO

625 Silver SW Suite 310

Albuquerque, NM 87102

Number: X - 88 - 02 - 107 - 3 TV 5

Telephone Number: 505-766-1486

Ten-Day Notice to the State of Utch, Division of Oil, Gas and Mining

You are notified that, as a result of a Federal inspection (4/26-27/88) (e.g. a federal inspection, citizen information, etc.) the Secretary has reason to believe that the person described below is in violation of the Act or a permit condition required by the Act. If the State Regulatory Authority fails within ten days after receipt of this notice to take appropriate action to cause the violation(s) described herein to be corrected, or to show cause for such failure and transmit notice of your action to the Secretary through the originating office designated above, then a Federal inspection of the surface coal mining operation at which the alleged violation(s) is occurring will be conducted and appropriate enforcement action as required by Section 521(a)(1) of the Act will be taken.

Permittee: Kaiser Coal, Inc.
(Or Operator if No Permit)

County: Carbon

Surface

Mailing Address: P.O. Box 10, Sny Side, Utah 84539

Underground

Permit Number: 007/012

Mine Name: Wellings ton Preparation Plant

Other Plant

NATURE OF VIOLATION AND LOCATION: Failure to protect side slopes of impoundments against erosion; west bank of the Auxiliary Pond

Section of State Law, Regulation or Permit-
Condition believed to have been violated: UMC 817.49(c)


NATURE OF VIOLATION AND LOCATION: Failure to divert surface drainage from the area above the coal processing waste pile, failure to divert surface runoff from the crest and face of the coal processing waste pile; the course

Coal Processing Waste Retain Pile East side of lower coal slurry pile
Section of State Law, Regulation or Permit UMC 817.83
Condition believed to have been violated: UMC 817.72(c)

NATURE OF VIOLATION AND LOCATION: Failure to provide for an appropriate combination of principal and emergency spillways at the slurry line sediment pond

Section of State Law, Regulation or Permit UMC 817.46(c)
Condition believed to have been violated:

Remarks or Recommendations:


MAY 2 1988

DIVISION OF
OIL, GAS & MINING

Date of Notice: 4-27-88
Not Certified on 4-29-88
Cert. Rec. # 121 613 527

Signature of Authorized Rep.: 
Print Name and ID: Rade H. Orell # 107

UNITED STATES DEPARTMENT OF THE INTERIOR
Office of Surface Mining
Reclamation and Enforcement
TEN-DAY NOTICE
(Continuation Sheet)

Original Office: Albuquerque Field Office
625 Silver SW Suite 510
Albuquerque, New Mexico 87102
Telephone Number:

Number X-88 -02 - 107 - 3 TV 5

Ten-Day Notice to the State of Utch, Division of Oil, Gas and Mining

NATURE OF VIOLATION AND LOCATION: Failure to use sediment control practices to reduce runoff volume and trap sediment; the north bank of the north dike of the upper Sherry cell + Failure to

provide slope protection Section of State Law, Regulation or Permit
Condition believed to have been violated: UMC 817.45(a)-(c)

NATURE OF VIOLATION AND LOCATION: to minimize erosion at the same site.

Section of State Law, Regulation or Permit
Condition believed to have been violated: UMC 817.83(c)

NATURE OF VIOLATION AND LOCATION: Failure to maintain records in the area of the mine; the "As-Built" certification for the Sherry Lake Sediment Pond

Section of State Law, Regulation or Permit
Condition believed to have been violated: UMC 840.14

NATURE OF VIOLATION AND LOCATION: _____

Section of State Law, Regulation or Permit
Condition believed to have been violated:

NATURE OF VIOLATION AND LOCATION: _____

Section of State Law, Regulation or Permit
Condition believed to have been violated:

Remarks or Recommendations: _____

Mailed Cert. on 4-27-88
Date of Notice: 4-27-88
Cert Rec. #
P 121 613 527

Signature of Authorized Rep: [Signature]
Print Name and ID: Rede H. Ours #107