



NO. N 88-27-1-1

To the following Permittee or Operator:

Name Kaiser Coal Corporation

Mine Wellington Prep. Plant Surface Underground Other

County Carbon State Utah Telephone 888-4421

Mailing Address P.O. Box 10, Sunnyside, Utah 84539

State Permit No. ACT/007/012

Ownership Category State Federal Fee Mixed

Date of inspection ~~April 26 and 27~~ April 26 and 27, 19 88

Time of inspection 8:00 a.m. p.m. to 1:00 a.m. p.m.

Operator Name (other than Permittee) Kaiser Coal Corporation

Mailing Address Same As Above

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailing April 27, 1988 Time of service/mailing 1:00 a.m. p.m.

Barry Groseley Mine Engineer
Permittee/Operator representative Title

B Groseley Reclamation Spec.
Signature Title

Harold G. Sandbeck # 27
Division of Oil, Gas & Mining representative Identification Number

Harold J. Hamblin
Signature

SEE REVERSE SIDE

WHITT-DOGDM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

2706



NOTICE OF VIOLATION NO. N 88-27-1-1

Violation No. 1 of 1

Nature of violation

Failure to maintain sediment control structures

Provisions of act, regulations or permit violated

817.45

Portion of operation to which notice applies

Spoil pile #2

Remedial action required (including any interim steps)

Repair berm.

Abatement time (including interim steps)

May 27, 1988 at 5:00 PM