

0021



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 14, 1988
9:00am - 11:00am

Permittee and/or Operators Name: Kaiser Coal Company
Business Address: P.O. Box D, Sunnyside, Utah 84539
Mine Name: Wellington Prep. Plant Permit Number: ACT/007/012
Type of Mining Activity: Underground Surface Other Prep. Plant
County: Carbon
Company Official (s): Barry Grosely
State Official(s): Lynn Kunzler and Daron Haddock
Partial: X Complete: Date of Last Inspection: 11/16-17/87
Weather Conditions: Clear and Cold
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469
Enforcement Action: Terminated N87-17-5-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	(X)
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION 01/14/88

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits. KCC submitted plans to provide sediment control and reclamation of the area affected subject to violation N87-17-5-1 and has provided a revised map showing this area as part of the permitted disturbed area. The Division's technical staff is currently reviewing these plans for adequacy.

2. Signs and Markers. The area subject to violation N87-17-5-1 has been properly identified and marked in the field with steel t-posts.


4d. Other Sediment Control Measures. The berm along the south side of the slurry pipeline corridor has been repaired as required by violation N87-17-5-1. A silt fence has been installed where runoff from the area subject to the referenced violation leaves the permit area.

12. Backfilling and Grading. The gully that existed in the fill along the slurry pipeline corridor has been backfilled and compacted.

Copy of this Report:

Mailed to: Brian Smith- DSM, Barry Grosely - KCC

Given to: Joe Helfrich & Sue Linner - DOGM

Inspectors Signature and Number:  #17 Date: 01/19/88