

7150  
12-18-89

0003



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*gd 512*

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: November 29, 1989  
8:00am - 10:00am

Permittee and/or Operators Name: Genwal Coal Company  
Business Address: Box 766, Wellington Utah, 84542  
Mine Name: Wellington Prep. Plant Permit Number: ACT/007/012  
Type of Mining Activity: Underground Surface Other Prep. Plant  
County: Carbon  
Company Official (s): Candy Manzanares  
State Official(s): Lynn Kunzler  
Partial: X Complete:          Date of Last Inspection: Oct. 11, 1989  
Weather Conditions: Clear and cold  
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( X )	( )	( )	( X )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( X )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( X )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( X )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

**INSPECTION REPORT**  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION 11/29/89

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers. The has ordered several signs to be placed within the area of new activity. These include a permit identification sign to be placed at the "y" of the new access road and topsoil stockpile identification signs to be placed on the new topsoil stockpiles.

3. Topsoil. New topsoil piles (one by the old refuse pile and one along the new access road) have been created in conjunction with the new construction. These piles have been bermed for protection. However, the operator was informed that these piles must be seeded to protect them against erosion this fall (prior to frozen ground conditions that would inhibit proper seeding).

4b. Diversions. The operator has completed the undisturbed drainage diversion along the westerly side of the permit area. Temporary perimeter markers have been placed on the out-by side, and will be replaced in the near future with steel posts. The operator was also told that the embankments and other disturbance associated with the construction of this diversion must be seeded this fall.

11. Contemporaneous Reclamation. Several sites were identified during the last inspection as requiring reseeding by November 10, 1989 (the topsoil pile on the east side of the property and the fill slopes along the slurry pipeline corridor). The operator had called the Division prior to the inspection and requested an extension to the November 10 deadline so that all seeding could be done at the same time. Since field conditions observed during the inspection were still favorable for seeding the extension was granted. However, the operator was cautioned that if seeding is not completed before ground or weather conditions are such that they would inhibit proper seeding, a violation would be issued.


16a. Road Construction. The operator has completed the construction of the new access road along the west side of the property. A permit identification sign has been ordered and will be installed at the "y" where the road connects to the newly constructed county road.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Candy Manzanares - GCC,

Gus Manwaring - GCC, PFO.

Given to: Joe Helfrich & Sue Linner - DOGM.

Inspectors Signature and Number:  #17 Date: 12/07/89