

0001



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*SU Jek*

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: January 25, 1990  
10:15am - 12:30pm

Permittee and/or Operators Name: Genwal Coal Company  
Business Address: Box 766, Wellington Utah, 84542  
Mine Name: Wellington Prep. Plant Permit Number: ACT/007/012  
Type of Mining Activity: Underground Surface Other Prep. Plant  
County: Carbon  
Company Official (s): Candy Manzanares  
State Official(s): Lynn Kunzler  
Partial: X Complete:          Date of Last Inspection: Dec. 6, 1989  
Weather Conditions: Clear and cold, no wind.  
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469  
Enforcement Action: None.

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( X )	( )	( )	( X )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( X )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( X )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION 1/25/90

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers. Permit identification signs have been installed and the phone number has been added to the sign. The temporary (wood stakes) disturbed area markers have been replaced with silver painted metal stakes. The topsoil identification signs have been delivered but did not have the topsoil pile identification number on them. The operator indicated that he would paint the numbers on himself rather than sending them back to the sign shop and that they would be installed by the end of the week.


3. Topsoil. All four topsoil piles have been seeded with the approved topsoil protection seed mix and were mulched with straw. The operator was in the process of repairing the protection berms that were damaged by the revegetation equipment and indicated that the work would be completed by the end of the week.

11. Contemporaneous Reclamation. All areas requiring contemporaneous revegetation were being seeded and mulched at the time of the inspection. It was expected that this work would be completed by early afternoon. Seed and mulch samples were collected by the Utah Department of Agriculture. Preliminary reports from the State seed lab indicated that there was no noxious weed seed in the samples taken. There was an excessive amount of wild oats (Avena fatua), a restricted weed, in the straw. However, they did not feel it would be a problem due to soil and climate conditions found on site.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Candy Manzanares - GCC,  
Gus Manwaring - GCC, PFO.

Given to: Joe Helfrich & Sue Linner - DOGM.

Inspectors Signature and Number:  #17 Date: 1/26/90