



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: August 1, 1990
8:40pm - 4:45pm

Permittee and/or Operators Name: Castle Valley Resources
Business Address: Box 766, Wellington Utah, 84542
Mine Name: Wellington Prep. Plant Permit Number: ACT/007/012
Type of Mining Activity: Underground Surface Other Prep. Plant
County: Carbon
Company Official (s): Candy Manzanares
State Official(s): Lynn Kunzler
Partial: Complete: X Date of Last Inspection: July 13, 1990
Weather Conditions: Clear to cloudy.
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	(X)	()
15. CESSATION OF OPERATIONS	(X)	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION 8/01/90

(Comments are Numbered to Correspond with Topics Listed Above)

4c. Sediment Ponds and Impoundments. All ponds and impoundments were found to be in proper working condition. Pond certifications were found to be in order. Weekly inspections of the upper slurry pond, the lower slurry pond and the clear water pond were current thru July 27, 1990, with no problems noted.

4d. Other sediment control measures. The site has several disturbed areas that do not report to a sediment pond. Alternative sediment control has been approved for all these areas. This inspection documented that all alternative sediment control measures for the site were in place and apparently functioning as designed.

4e. Surface and Groundwater Monitoring. All discharge points have been monitored with the proper reports filed. Points 1, 3, 4, 5, 6, 7, & 8 were all dry for the last quarter. Surface water monitoring was conducted as required. Samples were taken from point numbers 1 and 2. All other sample locations were dry.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Candy Manzanares - GCC.

Gus Manwaring - GCC, PFO.

Given to: Joe Helfrich & Daron Haddock, DOGM.

Inspectors Signature and Number:  #17 Date: 8/17/90