0016

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd

inspection report

Permit No. ACT/007/012

Inspection Date Oct 25, 1990

Permittee/Operator Name Genwal Coal Co./Castle Valley Resources Inc

Business Address P.O. Box 766

City Wellington State Utah Zip 84524

Mine Wellington Prep Plant ☐ Surface ☐ Underground ☒ Other

County Carbon State Utah

Company Official(s) Candy Manzanares

State Official(s) Daron Haddock

Time of Inspection 10:30 ☒ a.m. ☐ p.m. to 12:45 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection Sept. 7, 1990 Weather conditions warm + sunny

Acreage 1720 ☐ Permitted 356 ☐ Disturbed 1.5 ☐ Regraded 1.5 ☐ Seeded 469 ☐ Bonded

Enforcement Action NOV # N90-28-7-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☒	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT 007/012

Inspection Date Oct 25, 1990

Please number comments to correspond with topics on previous page.

1. Permits: A stipulation to the permit required the operator to submit updated maps & operation design details by Oct 1, 1990. This has not been done. NOV # N 90-28-7-1 was issued for not complying with the terms & conditions of the permit. the operator has until November 29, 1990 to submit the required information.

2. Signs & Markers: Identification signs, Topsoil markers, perimeter markers, Waste rock markers, were all found to be in place. The operator is in the process of getting new ID signs made. These will show Castle Valley Resources as the operator. The operator was informed to keep the Signs for Genwall Coal Co. up untill the permit has officially been ~~changed~~ transfered to Castle Valley Resources.

3. Topsoil: The topsoil piles were checked. No signs of erosion were apparent. Vegetation is very sparse on the piles which could

Copy of report mailed to

Copy of report given to

Inspector's signature Dave R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/012

Inspection Date Oct 25, 1990

Please number comments to correspond with topics on previous page.

be expected in this arid area. Vegetation should probably be looked at again next spring.

6. Development waste + spoil disposal: The course refuse pile was inspected. No visual signs of erosion were noticed at the toe of the pile even though the site has had two recent rain storms.

13. Revegetation: The area disturbed during the construction of the main by pass diversion appears to be doing well. Grasses are starting to grow in the areas that were seeded.

4c. Sediment Ponds:

The main facilities sediment pond was inspected. The recent rain storms have filled the pond to approximately 2 feet from the primary spillway. This is probably the first real test of the pond. It appears to be working satisfactorily.

Copy of report mailed to Brian Smith, OSM Candy Manzanares CVR Inc.

Copy of report given to Joe Helfrich

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE