0022

7770

Jch

DQH

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: December 11, 1990
8:30pm - 2:00pm

Permittee and/or Operators Name: Genwal Coal Company
Business Address: Box 766, Wellington Utah, 84542
Mine Name: Wellington Prep. Plant Permit Number: ACT/007/012
Type of Mining Activity: Underground____ Surface____ Other Prep. Plant
County: Carbon
Company Official (s): Jon Passic
State Official(s): Lynn Kunzler, Priscilla Burton and Sharon Falvey
Partial:____ Complete: X Date of Last Inspection: Nov. 30, 1990
Weather Conditions: Clear to cloudy.
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469
Enforcement Action: Terminated Nov #N90-17-8-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	(X)	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	(X)	( )	( )	(X)
f. EFFLUENT LIMITATIONS	(X)	( )	( )	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	( )	( )	( )
7. COAL PROCESSING WASTE	(X)	( )	( )	(X)
8. NONCOAL WASTE	(X)	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	(X)	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	(X)	( )	( )	( )
12. BACKFILLING AND GRADING	(X)	( )	( )	( )
13. REVEGETATION	(X)	( )	( )	( )
14. SUBSIDENCE CONTROL	(X)	( )	(X)	( )
15. CESSATION OF OPERATIONS	(X)	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	(X)	( )	( )	( )
b. DRAINAGE CONTROLS	(X)	( )	( )	( )
c. SURFACING	(X)	( )	( )	( )
d. MAINTENANCE	(X)	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	(X)	( )	( )	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	(X)	( )	( )	( )

an equal opportunity employer

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER: ACT/007/012 DATE OF INSPECTION 12/11/90

(Comments are Numbered to Correspond with Topics Listed Above)

4c. Sediment Ponds and Impoundments. The inlet to the slurry pipeline pond has been repaired. Pond certifications were found to be in order. Weekly inspections of the upper slurry pond, the lower slurry pond and the clear water pond were current with no propblems noted.

4e. Surface and Groundwater Monitoring. All discharge points have been monitored with the proper reports filed. Points 1, 3, 4, 5, 6, 7, & 8 were all dry for the last quarter. Surface water monitoring was conducted as required. Samples were taken from point numbers 1 and 2. All other sample locations were dry.

. Coal Processing Waste. Quarterly inspections of the coal processing waste and coarse slurry piles were current with no problems noted.

Copy of this Report:
Mailed to: Brian Smith - OSMRE, Candy Manzanares - GCC,
Given to: Joe Helfrich & Daron Haddock, DOGM.

Inspectors Signature and Number: #17 Date: 1/3/91