

Genwall Coal/Castle Valley Resources, Inc.
Wellington Preparation Plant

MSHA I.D. #42-00099

Coal Refuse Piles

Quarterly Report

SITE NAME: Wellington Preparation Plant
P.O. Box 766
Wellington, UT 84542

<u>Refuse Pile</u>	<u>Pile ID #</u>
Pond Refuse Pile	1211-UT-09-00099-05
Plant Refuse Pile	1211-UT-09-00099-01

Water impounding against toe: None

Fires on piles: None

Seepage, cracks, erosion problems or any other comments pertaining to the stability of the pile: No significant* erosion problems noted at this time. Facilities appear to be stable.

*Deeper than 9 inches

I do hereby certify that all work and maintenance performed on the above refuse piles were done according to the approved design and plans.



Richard M. Noble
Name
1/19/91
Date

Franson-Noble & Associates, Inc.

cc: C. Manzanarez (Plant File)

**Genwall Coal/Castle Valley Resources, Inc.
Wellington Preparation Plant**

MSHA I.D. #42-00099

Quarterly Pond Report

This report addresses the following ponds:

<u>POND</u>	<u>CAPACITY</u> (cubic feet)	<u>INSTRUMENTATION</u>
Sediment #1	74,592	3 Depth Poles
Roadside	24,603	None
Auxiliary	34,265	None
Dryer	9,747	None
Pipeline Slurry	47,044	None
Upper Refuse	Unknown	None
Lower Refuse	52,272,000	None
Clear Water	8,058,600	None

<u>PONDS</u>	<u>SEDIMENT</u> (cubic feet)	<u>WATER</u> (cubic feet)	<u>EXISTING STORAGE</u> <u>CAPACITY</u> (%)
Sediment	None	Puddle	100
Roadside	144	Dry	99
Auxiliary	464	Dry	99
Dryer	26	Dry	100
Pipeline Slurry	70	Dry	100
Upper Refuse	Unknown	Dry	Unknown
Lower Refuse	43,560,000 ¹	Dry	17
Clear Water	Unknown	Dry	Unknown

¹ Estimated

Fires in Impoundments: No evidence of fires or heat was noted.

