

0017



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*Handwritten initials/signature*

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: June 21, 1991  
11:30 am to 3:00 pm

Permittee and/or Operators Name: Genwal Coal Company  
Business Address: P.O. Box 766, Wellington, Utah 84528  
Mine Name: Wellington Prep Plant Permit Number: ACT/007/012  
Type of Mining Activity: Underground Surface OtherXX  
County: Carbon  
Company Official (s): Candy Manzanares  
State Official(s): David W. Darby  
Partial: XX Complete:            Date of Last Inspection: May 30, 1991  
Weather Conditions: Cold, clear  
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	(X)
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

**INSPECTION REPORT**

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 06-21-91

(Comments are Numbered to Correspond with Topics Listed Above)

**1. Permit**

The Division has been actively working with Genwal Coal Company, a subsidiary of NEICO, toward completing stipulation UMC 788.14-(1)-SCL which requires submittal of information according to a specific schedule. A letter received from Patrick Collins, Ph.D., Mount Nebo Scientific indicated a time schedule for compliance and a date of September 1, 1991 for submittal of the updated Operation and Reclamation Plan.

On April 25, 1991 the Division received plans from Genwal Coal Company, through Patrick Collins, requesting a permit amendment for a project designed to determine feasibility for removing coal fines at the prep plant. This plan is has been reviewed for completeness by the Division staff. Comments were compiled and sent to the operator on June 19, 1991.

**4. Hydrologic Balance**

**b. Diversions**

All disturbed and undisturbed diversions, berms and culverts were checked for integrity. They all appeared intact and capable of conveying the design flows.

c. The embankments of the sedimentation ponds and tailings pond were checked for integrity. All appeared intact with no erosion or structural defects.

The sedimentation pond contained some water, but was below the decant level.

**Copy of this Report:**

Mailed to: Candy Manzanares, CVR; Brian Smith, OSM  
Given to: Joe Helfrich, DOGM; Darron Haddock DOGM

Inspectors Signature & Number: *David W. Daryl* # 18 Date: 07-02-91