



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

pk 10/27

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 16, 1991
9:00 a.m. to 12:00 p.m.

Permittee and/or Operators Name: Genwal Coal Company
Business Address: Box 766, Wellington, Utah 84542
Mine Name: Wellington Prep. Plan Permit Number: ACT/007/012
Type of Mining Activity: Underground Surface _____ Other X
County: Carbon
Company Official(s): Jon Passic (office portion)
State Official(s): Rick Summers
Partial: x Complete: _____ Date of Last Inspection: 6/21/91
Weather Conditions: hot, fair
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469
Enforcement Action: none.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 7/16/91

(Comments are Numbered to Correspond with Topics Listed Above)

1. **PERMITS:**

I met with Jon Passic at the Wellington site office. We discussed the recent merger of NEICO and IPA. A portion of the permit area will be owned solely by NEICO and a portion owned jointly w/IPA. They plan to call the merged group the Crandall Canyon Project. Castle Valley Resources will act as the operator with no land ownership. Mr. Passic was scheduled to meet with Lowell Braxton to discuss the permit transfer and related permitting actions.

4. **HYDROLOGIC BALANCE:**

c. SEDIMENT PONDS AND IMPOUNDMENTS:

The sediment ponds were inspected and contained no water. No problems were noted. During the 5/30/91 complete inspection of the mine, it was noted that the 1st quarter pond inspections were not located at the office. During this inspection, Mr. Passic located the reports and they appeared to be in order.

e. SURFACE AND GROUNDWATER MONITORING:

As with the pond inspections, the 1st quarter water monitoring reports were unavailable during the last complete. During this inspection, they were located and reviewed.

6. **DISPOSAL OF DEVELOPMENT WASTE & SPOIL:**

Material from the Crandall Canyon Mine has recently been disposed of on the plant area refuse pile.

Copy of this Report:

Mailed to: Candy Manzanares (GCC), Brian Smith (OSM)

Given to: Daron Haddock, Joe Helfrich (DOGM)

Inspectors Signature & Number:  #15 Date: 7/18/91