



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

gck

INSPECTION REPORT

INSPECTION DATE & TIME: 2/18/91
10:00 am to 4 pm

Permittee and/or Operator's Name: Genwal Coal Company
Business Address: Box 766, Wellington, UT, 84542
Mine Name: Wellington Prep. Plant Permit Number: Act 007/012
Type of Mining Activity: Underground Surface Other x
County: Carbon Company Official(s): Jon Passic
State Officials(s): Sharon Falvey, Steve Demczak
Federal Official(s): none
Partial: Complete x Date of last Inspection: 12/11/90
Weather Conditions: Windy, Partly Cloudy
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5
Bonded 469 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	(x)
2. SIGNS AND MARKERS	(x)	()	()	()
3. TOPSOIL	(x)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(x)	()	()	()
b. DIVERSIONS	(x)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(x)	()	()	(x)
f. EFFLUENT LIMITATIONS	(x)	()	()	()
5. EXPLOSIVES	()	()	(x)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	(x)	()	()	()
7. COAL PROCESSING WASTE	(x)	()	()	()
8. NONCOAL WASTE	(x)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(x)	()	()	()
10. SLIDES AND OTHER DAMAGE	(x)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(x)	()	()	()
12. BACKFILLING AND GRADING	(x)	()	()	()
13. REVEGETATION	(x)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(x)	()
15. CESSATION OF OPERATIONS	(x)	()	()	()
16. ROADS				
a. CONSTRUCTION	(x)	()	()	()
b. DRAINAGE CONTROLS	(x)	()	()	()
c. SURFACING	(x)	()	()	()
d. MAINTENANCE	(x)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(x)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(x)	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 2/8/91

(Comments are Numbered to Correspond with Topics Listed Above)

1. The permittee submitted a revised PAP to the division January 28, 1991 to meet permit requirements. The PAP submitted is currently under review.

4. On January 19, 1991 all sediment ponds, impoundments, and refuse piles were inspected with no noted instability. Ground Water and Surface Water sampling was completed on 1/14/91. No discharge was reported at UPDES discharge points.

Copy of this Report:

Mailed to: Brian Smith (OSM), Candy Manzanares GCC

Given to: Joe Helfrich and Daron Haddock DOGM

Inspector's Signature & Number: Sharon K. Fahney #38 Date: 2/25/91