

0030



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertor
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

RECEIVED
JAN 30 1991

1027
gd

PERMIT NO.: ACT/007/012
Inspection Date: January 25, 1991

Permittee and/or Operators Name: Genwal Coal Company
Business Address: Box 766
City: Wellington State: Utah Zip: 84542
Mine Name: Wellington Prep Plant County: Carbon State: Utah
Type of Mining Activity: Underground XX Surface Other
Company Official (s): Candy Manzanares
State Officials (s): Stephen J. Demczak
Time of Inspection: 10:00 (X)a.m. () p.m. to 12:01 ()a.m. (X)p.m.
Partial XX Complete: Date of Last Inspection: Dec. 11, 1990
Weather Conditions: Cool/4" Snow
Acreage: Permitted 1720 Disturbed Regraded 356 Seeded 1.5
Bonded 469 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	(X)
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/012 INSPECTION DATE January 25, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL:

Topsoil storage areas showed no signs of erosion due to snow cover. Signs were located on piles and berms were intact.

4. HYDROLOGIC BALANCE:

c. Sediment Ponds And Impoundments:

All ponds were checked for stability and erosion which appeared to be in good condition.

6. DEVELOPMENT WASTE AND SPOIL DISPOSAL:

The coarse refuse pile was inspected. No signs of erosion were noticed. The refuse pile has the necessary identification sign.

Copy of report:

Mailed to: Candy Manzanares (GCC)

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39 Date: 1/25/91

Stephen J. Demczak