



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Handwritten initials/signature

INSPECTION REPORT

INSPECTION DATE & TIME: 28 July, 1992
1:30 p. m. to 3:00 p. m.

Permittee and/or Operator's Name: Castle Valley Resources
Business Address: P. O. Box 766, Wellington, Utah 84542
Mine Name: Wellington Prep Plant Permit Number: ACT/0157012
Type of Mining Activity: Underground Surface Other X
County: Carbon
Company Official(s): Jay Marshall
State Officials(s): James D. Smith
Federal Official(s): none
Partial: X Complete: Date of last Inspection: June 10, 1992
Weather Conditions: Sunny, high 80's, light breeze
Acreage: Permitted- 1720 Disturbed- 356 Regraded- 1.5 Seeded- 1.5 Bonded-
469 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(X)	()	()	(X)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/⁰⁰⁷015/012 DATE OF INSPECTION: July 28, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers

The previous inspection found a sign at the slurry pond that had been vandalized by gunfire. This sign has been replaced and moved farther from the point of public access. The sign was visible from that point of public access but not all information on the sign could be clearly read from that distance.

4.b. Diversions

Culverts along the plant railroad system have been cleared with a backhoe recently, with catchment basins left at both ends of the culverts.


8. Non-Coal Waste

Sediment from the sediment pond at the Convulsion Canyon Mine is temporarily stored on the coarse refuse pile adjacent to the Wellington Plant. An amendment to the current MRP has been submitted to DOGM to permit this to become the permanent disposal site for this material.

Copy of this Report:

Mailed to: Brian Smith-OSM, Jay Marshall-Genwall Coal Co.

Given to: Joe Helfrich-DOGM, Damon Haddock-DOGM

Inspector's Signature:  # 43 Date: July 30, 1992



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

ADZ
Jan

INSPECTION REPORT

INSPECTION DATE & TIME: June 10, 1992
11:50 a.m. to 3:30 p.m.

Permittee and/or Operator's Name: Castle Valley Resources
Business Address: P.O. Box 766, Wellington, Ut 84542
Mine Name: Wellington Prep. Plant Permit Number: ACT/007/012
Type of Mining Activity: Underground Surface Otherx
County: Carbon Company Official(s): Candy Manzanares
State Officials(s): Wayne H. Western
Federal Official(s): none
Partial: x Complete: Date of last Inspection: May 22, 1992
Weather Conditions: Light cloud cover temp. 70's to 80's
Acreage: Permitted-1720 Disturbed-356 Regraded-1.5 Seeded-
1.5 Bonded-469 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	()
2. SIGNS AND MARKERS	(x)	()	()	()
3. TOPSOIL	(x)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(x)	()	()	()
b. DIVERSIONS	(x)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(x)	()	()	()
f. EFFLUENT LIMITATIONS	(x)	()	()	()
5. EXPLOSIVES	(x)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	(x)	()	()	()
7. COAL PROCESSING WASTE	(x)	()	()	()
8. NONCOAL WASTE	(x)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(x)	()	()	()
10. SLIDES AND OTHER DAMAGE	(x)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(x)	()	()	()
12. BACKFILLING AND GRADING	(x)	()	()	()
13. REVEGETATION	(x)	()	()	()
14. SUBSIDENCE CONTROL	(x)	()	()	()
15. CESSATION OF OPERATIONS	(x)	()	()	()
16. ROADS				
a. CONSTRUCTION	(x)	()	()	()
b. DRAINAGE CONTROLS	(x)	()	()	()
c. SURFACING	(x)	()	()	()
d. MAINTENANCE	(x)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(x)	()	()	()
18. SUPPORT FACILITIES	(x)	()	()	()

UTILITY INSTALLATIONS

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT 007/012 DATE OF INSPECTION: June 10, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits

All permits and supporting documents are scheduled to be transferred to Castle Valley Resources', Genwal Coal Company's office in Huntington, Utah on June 13, 1992. Candy Manzanares, Wellington's former resident agent, recommended that when inspectors get to Price that they call the Genwal office so that the current resident agent can bring the documents to the site.

2. Signs and Markers

A sign for the slurry pond had been vandalized by a shotgun blasts. Mr. Manzanares has a replacement sign and it's frame is ordered. Mr. Manzanares want to change the signs location to reduce vandalism. Changing the sign's location is permitted so long as it is visible from the point of public entry.

Copy of this Report:

Mailed to:

John Kathmann (OSM), Candy Manzanares

Given to:

Joe Helfrich and Daron Haddock (DOGM)

Inspector's Signature: *Wayne L. Stevens* #42 Date: 6/15/92