



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

*DRH  
gm*

Permit No. ACT/007/012 Inspection Date: January 30, 1992  
 Permittee and/or Operators Name: Genwal Coal Co. Castle Valley Resources Inc.  
 Business Address: P.O. Box 766 City: Wellington State: UT Zip: 84542  
 Mine Name: Wellington Prep Plant County: Carbon State: Utah  
 Type of Mining Activity: Underground Surface Other XX  
 Company Officials: Jon Passic State Officials: Stephen J. Demczak  
 Time of Inspection: 9:00 a.m. - 11:15 a.m. Partial X Complete:         
 Acreage: Permitted 1,720 Disturbed 356 Regraded 1.5  
 Seeded 1.5 Bonded 469 Date of Last Inspection: December 17, 1991  
 Weather Conditions: Teens/Snow Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. <u>PERMITS</u>	( )	( )	( )	( )
2. <u>SIGNS AND MARKERS</u>	( X )	( )	( )	( X )
3. <u>TOPSOIL</u>	( X )	( )	( )	( X )
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	( )	( )	( )	( )
b. <u>DIVERSIONS</u>	( )	( )	( )	( )
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	( X )	( )	( )	( X )
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	( )	( )	( )	( )
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	( )	( )	( )	( )
f. <u>EFFLUENT LIMITATIONS</u>	( )	( )	( )	( )
5. <u>EXPLOSIVES</u>	( )	( )	( )	( )
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	( )	( )	( )	( )
7. <u>COAL PROCESSING WASTE</u>	( )	( )	( )	( )
8. <u>NONCOAL WASTE</u>	( )	( )	( )	( )
9. <u>PROTECTION OF FISH, WILDLIFE AND     RELATED ENVIRONMENTAL VALUES</u>	( )	( )	( )	( )
10. <u>SLIDES AND OTHER DAMAGE</u>	( )	( )	( )	( )
11. <u>CONTEMPORANEOUS RECLAMATION</u>	( )	( )	( )	( )
12. <u>BACKFILLING AND GRADING</u>	( )	( )	( )	( )
13. <u>REVEGETATION</u>	( )	( )	( )	( )
14. <u>SUBSIDENCE CONTROL</u>	( )	( )	( )	( )
15. <u>CESSATION OF OPERATIONS</u>	( )	( )	( )	( )
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	( )	( )	( )	( )
b. <u>DRAINAGE CONTROLS</u>	( )	( )	( )	( )
c. <u>SURFACING</u>	( )	( )	( )	( )
d. <u>MAINTENANCE</u>	( )	( )	( )	( )
17. <u>OTHER TRANSPORTATION FACILITIES</u>	( )	( )	( )	( )
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	( )	( )	( )	( )
19. <u>AVS Check</u>	( )	( )	( )	( )

Permit No. ACT/007/012 Inspection Date January 30, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers -

The perimeter markers were apparent and easily seen from the main haul road going to the preparation plant.

3. Topsoil -

The topsoil piles were intermittently covered with snow, and the circumference of the piles were bermed and stable. There were no signs of wind or water erosion effecting the topsoil piles.

4c. Sediment Ponds and Impoundments -

At the time of inspection, the ponds were not discharging. The sediment ponds did contain small amounts of water which were frozen over. The embankments were partially snow covered, but there were no signs of erosion.

Copy of report:

Mailed to: Genwal Coal Co.Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: February 3, 1992

Inspector's Signature and Number:

Stephen J. Demczak  
Stephen J. Demczak

#39