



027
JH

NO. N 92-38-1-1

To the following Permittee or Operator:

Name Castle Valley Resources

Mine Wellington Preparation Plant Surface Underground Other

County CARBON State UT Telephone 687-9714

Mailing Address P.O. Box 766, WELLINGTON UT 84524

State Permit No. ACT/007/012

Ownership Category State Federal Fee Mixed

Date of inspection 12/17/91, 1991

Time of inspection 10:00 a.m. p.m. to 12:50 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 1/6/92

Time of service/ mailing 10:00 a.m. p.m.

Permittee/Operator representative _____

Title _____

Signature _____

Sharon K Falvey
Division of Oil, Gas & Mining representative

Reclamation Hydrologist
Title

Sharon K Falvey
Signature

38
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N92-38-1-1

Violation No. 1 of 1

Nature of violation

Failure to provide certified report promptly to the Division following inspection of the refuse.

Failure to maintain coarse refuse as designed and in accordance with the approved plan and RB14 rules.

Failure to include appearances of instability, structural weakness and other hazardous conditions. (6 ft gullies noted as not greater than 9 inches).

Provisions of act, regulations or permit violated

RB14-301-514.230 , RB14-301-746.221

Portion of operation to which notice applies

POND Refuse Pile MSHA ID 1211-UT-09-0099-05
 North of access road, South portion of Refuse
 has approximately 6 ft gullies.

Remedial action required (including any interim steps)

- ① Provide Existing Quarterly Reports to the Division (for the third Quarter)
- ② Provide an amendment to the plan including methods to re stabilize and prevent AREAS OF gully formation according to the RB14 Regulations.

Abatement time (including interim steps)

① SEVEN DAYS, January 10, 1992

② Sixty Days, March 3, 1992