



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

*gh* *10/27*

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial:      Complete: XX Exploration     

Inspection Date/Time: November 25, 1993/08:30am-03:30pm

Date of Last Inspection: October 12, 1993

Mine Name: Wellington Prep Plant County: Carbon Permit Number: ACT/007/012 12/2  
 Permittee and/or Operator's Name: Castle Valley Resources  
 Business Address: P. O. Box 1282, Huntington, UT 84528  
 Type of Mining Activity: Underground      Surface      Prep. Plant XX Other       
 Officials(s): State: Stephen J. Demczak Company: Candy Manzanares  
 Federal Official(s):      Weather Conditions: Cold/Snow  
 Existing Acreage: Permitted-1720 Disturbed-356 Regraded-1.5 Seeded-1.5 Bonded-744  
 Increased/Decreased: Permitted-     Disturbed-     Regraded-     Seeded-     Bonded-      
 Status:      Exploration/ X Active/      Inactive/      Temp Cessation/      Bond Forfeiture  
 Reclamation (      Phase I/      Phase II/      Final Bond Release/      Liability      Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2. SIGNS AND MARKERS	[XX]	[ ]	[XX]	[ ]
3. TOPSOIL	[XX]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[ ]	[ ]
d. WATER MONITORING	[XX]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[XX]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[XX]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[XX]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[XX]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[XX]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[XX]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[XX]	[ ]	[ ]	[ ]
13. REVEGETATION	[XX]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[XX]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[XX]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[XX]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[XX]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	[ ]	[XX]	[ ]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[XX]	[ ]	[XX]	[ ]
20. AIR QUALITY PERMIT	[XX]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[XX]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/012 DATE OF INSPECTION: November 25, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

- a) The insurance policy number 3710-3989 and will expire January 1, 1994 with aggregate \$2,000,000 and each occurrence \$1,000,000. The policy does cover explosives.
- b) The sediment ponds were inspected on September 30, 1993 with no hazardous conditions existing. The report was P. E. Certified.
- c) Refuse piles were inspected quarterly and P. E. Certified with no hazardous conditions existing.
- d) The MSHA ponds were weekly inspected. The last inspection was November 19, 1993 with no hazardous conditions existing.

2. Signs and Markers -

The identifications signs have not been changed and are correct with the MRP. A permit transfer application has been submitted to the Division and is under the review process.

4a. Diversions -

There has not been sufficient rainfall since early fall. The diversions are intact, not eroded and have no performance problems.

4b. Sediment Ponds -

The sediment ponds were nearly dry, therefore, there was no discharging of water out of the outlet. There were no signs of erosion of inlets, outlets or embankments.

INSPECTION REPORT  
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/012 DATE OF INSPECTION: November 25, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

17. Support Facilities -

The coal storage yard has been extended and the boundaries are not clear on the surface facility map. The map should indicate clear boundaries of the coal storage pile. An update is needed by next inspection.

19. AVS Check -

An AVS check has been taken at the mine site with no new changes in ownership and control.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Castle Valley Resources, Candy Manzanares

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: December 2, 1993

Inspector's Signature and Number: \_\_\_\_\_

Stephen J. Demczak  
Stephen J. Demczak

#39