



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Michael O. Leavitt
Governor
Lowell P. Braxton
Division Director

Partial: XXX Complete: Exploration:
Inspection Date & Time: 1/26/2000 / 8:15a.m.-9:30a.m.
Date of Last Inspection: 12/28/99

Mine Name: Centennial Project County: Carbon Permit Number: ACT/007/019
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P.O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Mike Glasson
State Officials(s): Peter Hess Federal Official(s): None
Weather Conditions: Snowing, 4" Fresh snow
Existing Acreage: Permitted- 5179.49 Disturbed- 35.27 Regraded- Seeded- Bonded- 35.27
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 1/26/2000

(Comments are Numbered to Correspond with Topics Listed Above)

Note: The site had received four inches of fresh snow overnight, with additional accumulation rapidly growing. Coal trucks were bogging down en route to the Mine.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The permittee has not submitted a revised Plate 6, (surface drainage map), to show ditch DD-2A, and the twelve inch culvert 200 feet north of the Pinnacle Mine truck loadout hopper. The permittee committed to revising Plate 6 during the November '99 inspection. Failure to supply this simple amendment creates a potential compliance situation.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Notice of Violation N2000-46-1-1, "Missing Water Monitoring Information", for not submitting monitoring information relative to surface monitoring site 12-1 in Alrad Canyon, and ground water monitoring point Well #1 was terminated on January 31, 2000.

16B. ROADS: DRAINAGE CONTROLS

The road drainage controls which were capable of being inspected this day appeared to be capable of functioning as designed.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Henry Austin (OSM)

Given to: Pam Grubaugh-Littig (DOGM)

Filed to: Price Field Office

Date: February 1, 2000

Inspector's Signature: _____

Peter Hess
Peter Hess

#46