



**State of Utah**  
 DEPARTMENT OF NATURAL RESOURCES  
 DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
 Governor  
 Kathleen Clarke  
 Executive Director  
 Lowell P. Braxton  
 Division Director

1594 West North Temple, Suite 1210  
 PO Box 145801  
 Salt Lake City, Utah 84114-5801  
 801-538-5340  
 801-359-3940 (Fax)  
 801-538-7223 (TDD)

*Phil  
 but  
 JD*  
 OK

**INSPECTION REPORT**

Partial XXX Complete    Exploration     
 Inspection Date: 07/26/2002 Time: 10:00am-2:30pm  
 Date of Last Inspection: 06/28/2002

Mine Name: Wellington Prep Plant County: Carbon Permit Number: C/007/012  
 Permittee and/or Operator's Name: Nevada Electric Investment Company (NEICO)  
 Business Address: c/o Mt. Nebo Scientific, P.O. Box 337, Springville, Utah 84663  
 Company Official(s): Patrick Collins  
 State Official(s): Stephen J. Demczak Federal Official(s): None  
 Weather Conditions: Warm, 80's, cloudy  
 Type of Mining Activity: Underground    Surface    Prep Plant XXX Other     
 Existing Acreage: Permitted 1573.5 Disturbed 392 Regraded    Seeded     
 Status: Active

**REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT  
(Continuation Sheet)

PERMIT NUMBER: C/007/012

DATE OF INSPECTION: 07/26/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

**1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE**

The permittee will be under going a mid-term review. A site visit is planned for August 7, 2002. The Division will be inspecting BTCA areas during the site visit.

**4A. HYDROLOGIC BALANCE: DIVERSIONS**

Diversions were inspected and complied with the performance standards. There has been little or no water flowing within the diversions this summer.

**4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS**

The upper and lower slurry ponds contain water. The permittee is filling the ponds up. This is to prevent the possibility of coal dust leaving the site.

**4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES**

Alternate sediment control areas were inspected and along the railroad tracks some straw could be replaced. The agent of the permittee will replace the straw bales.

**4D. HYDROLOGIC BALANCE: WATER MONITORING**

The permittee was informed that the Division would not accept "No access" to the water-monitoring sites as a way of complying with the requirements of the MRP and the R645 Coal Rules.

The permittee has submitted first quarter water monitoring electronically to the Division.

**7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS**

The refuse piles were inspected and no hazardous conditions were noticed.

**8. NONCOAL WASTE**

The disturbed area was clear of non-coal waste material.

**9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES**

A fox was seen running through the disturbed area.

**18. SUPPORT FACILITIES/UTILITY INSTALLATIONS**

No construction has taken place since the last inspection.

Inspector's Signature: \_\_\_\_\_

*Stephen J. Demczak*  
Stephen J. Demczak #39

Date: August 1, 2002

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM  
Patrick Collins, Mt. Nebo for NEICO  
Price Field office

O:\007012.WEL\Compliance\2002\p\_0726.doc