



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Role, Name. Row 1: OGM Priscilla Burton Environmental Scientist III. Row 2: Company Patrick D. Collins Resident Agent.

Inspection Report

Table with 2 columns: Field, Value. Fields include Permit Number (C0070012), Inspection Type (PARTIAL), Inspection Date (Wednesday, May 11, 2005), Start Date/Time (5/11/2005 12:00:00 PM), End Date/Time (5/11/2005 2:30:00 PM), Last Inspection (Thursday, April 28, 2005).

Inspector: Priscilla Burton, Environmental Scientist III

Weather: overcast upper 40's

InspectionID Report Number: 607

Accepted by: whedberg
6/8/2005

Permittee: NEVADA ELECTRIC INVESTMENT CO
Operator: NEVADA ELECTRIC INVESTMENT CO
Site: WELLINGTON PREPARATION PLANT
Address: 330 E 400 S STE 6, PO BOX 337 SPRINGVILLE UT 84663
County: CARBON
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Rows: 1,573.50 Total Permitted; 392.00 Total Disturbed; Phase I; Phase II; Phase III.

Mineral Ownership

- checkbox Federal
checkbox State
checkbox County
checkbox Fee
checkbox Other

Types of Operations

- checkbox Underground
checkbox Surface
checkbox Loadout
checkbox Processing (checked)
checkbox Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Rain previous night has swollen the Price River and overtopped the silt fence at the recently reclaimed river pumphouse. Ironically, recently seeded areas were dry.

Inspector's Signature

Date Monday, May 16, 2005

Priscilla Burton, Environmental Scientist III
Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

3. Topsoil

Topsoil pile #4 by slurry ponds was well vegetated. Many new greasewood seedlings. Also noted evening primrose, Sueda, either great Basin or Russian Wildrye, mustard, and Malcolmea (purple flowered). Unofficial estimate of all vegetative cover on the topsoil pile is 65% (photo attached).

4.a Hydrologic Balance: Diversions

Walked Siaperas ditch, silt fence in good condition.

4.c Hydrologic Balance: Other Sediment Control Measures

Price River had overtopped the silt fence at the river's edge in the vicinity of the river pumphouse reclamation. This silt fence will be repaired as soon as the river subsides (photo attached)

4.d Hydrologic Balance: Water Monitoring

Although the Price River was running extremely high, there was no discharge from SW 2 on the west side of the river or from SW 4 in the vicinity of the Siaperas ditch (see Dwg 621a for monitoring point locations).

9. Protection of Fish, Wildlife and Related Environmental Issues

Two mule deer in Siaperas ditch. A pair of Western Kingbirds were along road to slurry ponds (gray with yellow chest and underwing feathers).

11. Contemporaneous Reclamation

River pumphouse reclamation was dry except in vicinity of pumphouse which is a bog. A copy of the seed mix for the river pumphouse and the Covol wash plant area was received on May 6, 2005 and is document 0010 in the 2005 incoming folder.

