



The State of Utah

Department of
Natural ResourcesDivision of
Oil, Gas & MiningROBERT L. MORGAN
*Executive Director*LOWELL P. BRAXTON
*Division Director*OLENE S. WALKER
*Governor*GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:

Company	Patrick D. Collins	Resident Agent
OGM	Steve Demczak	Environmental Scientist III

Inspection Report

Permit Number:	C0070012
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, July 31, 2007
Start Date/Time:	7/31/2007 10:00:00 AM
End Date/Time:	7/31/2007 3:00:00 PM
Last Inspection:	Friday, June 15, 2007

Inspector: Steve Demczak, Environmental Scientist IIIWeather: Sunny, 90'sInspectionID Report Number: 1391Accepted by: dhaddock *OK*
9/12/2007Permittee: **NEVADA ELECTRIC INVESTMENT CO**Operator: **NEVADA ELECTRIC INVESTMENT CO**Site: **WELLINGTON PREPARATION PLANT**Address: **330 E 400 S STE 6, PO BOX 337 SPRINGVILLE UT 84663**County: **CARBON**Permit Type: **PERMANENT COAL PROGRAM**Permit Status: **ACTIVE**

Current Acreages

1,573.50	Total Permitted
392.00	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
 State
 County
 Fee
 Other

Types of Operations

- Underground
 Surface
 Loadout
 Processing
 Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The Permittee's site representative notified the Division on April 30, 2007 that the required quarterly surface/ ground and UPDES water monitoring information for the first quarter of 2007 was in the DOGM data base "pipeline" and that the information was acceptable for uploading. Field data gathering for first quarter of 2007 was performed on March 14, 2007. The Permittee continues to meet the Special Condition included in Attachment "A" of the current State permit. There are no pending compliance actions.

According to Mr. Collins, Wellington Prep has received approval from MSHA to conduct monthly inspection of the slurry ponds instead of weekly inspections.

Inspector's Signature:

Steve Demczak
 Steve Demczak, Environmental Scientist III
 Inspector ID Number: 39

Date

Thursday, August 30, 2007

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!
 Where ideas connect™

Permit Number: C0070012
 Inspection Type: PARTIAL
 Inspection Date: Tuesday, July 31, 2007

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

No permitting action is pending. The site is not active.

2. Signs and Markers

Signs and markers were inspected. The information meets the R645 requirements.

4.a Hydrologic Balance: Diversions

The diversions were spot inspected and would function during a rain storm.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds were inspected with no hazardous conditions noticed during the inspection.

7. Coal Mine Waste, Refuse Piles, Impoundments

The slurry ponds and refuse piles were inspected with no hazardous condition noticed during the inspection.

18. Support Facilities, Utility Installations

No new support facilities were constructed.