



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0070012
Inspection Type:	COMPLETE
Inspection Date:	Thursday, December 12, 2013
Start Date/Time:	12/12/2013 9:00:00 AM
End Date/Time:	12/12/2013 4:00:00 PM
Last Inspection:	Thursday, September 26, 2013

Representatives Present During the Inspection:	
Company	Patrick Collins
OGM	Steve Demczak

Inspector: Steve Demczak

Weather: Sunny, 12 DEG, snow covered

InspectionID Report Number: 3702

Accepted by: jhelfric

12/30/2013

Permittee: **PRICE RIVER TERMINAL, LLC**
 Operator: **WATCO TRANSLOADING, LLC**
 Site: **WELLINGTON PREPARATION PLANT**
 Address: **PO BOX 337, SPRINGVILLE UT 84663**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

1,573.50	Total Permitted
392.00	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee is has installed a single wide trailer outside the disturb area. This is use as the mail office. The training tracks have been reconditioned to handle oil rail cars. The dirt road to the office and oil loading area has been improved. The disturb area has not been effected by the new installation of trans-loading of crude oil. This activity is not mining related.

There is no activity within the disturb area.

Stephen J.
Demczak

Digitally signed by Stephen J. Demczak
 DN: cn=Stephen J. Demczak, o, ou,
 email=stevdemczak@utah.gov, c=US
 Date: 2014.01.29 13:05:12 -07'00'

Inspector's Signature:

Steve Demczak,
 Inspector ID Number: 39

Date Thursday, December 12, 2013



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permit was transferred on November 12, 2013. The bonding amount is \$4,142,000. The permit will expire on December 9, 2013. The permittee is named Price River Terminal. The permittee has a new UPDES Permit #DWQ-2013-0005358.

2. Signs and Markers

The permittee installed new identifications from roads leading to public access. The information contains within the signs meet the R645 Coal Rules. They have also installed new MSHA signs.

3. Topsoil

The topsoil piles are snow covered. I did not see any signs of wind or water erosion.

4.a Hydrologic Balance: Diversions

The diversions were open and functioning as design. Most diversions were snow covered. No water was flowing within the diversions due to the cold temperatures.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds were inspected in the first quarter on November 12, 2013. This was the annual sediment pond inspection. This report is P.E. certified. No hazardous conditions were reported. I did not see any hazardous conditions during the inspection. All sediment ponds contained water. No sediment pond was discharging during the inspection.

4.d Hydrologic Balance: Water Monitoring

The permittee has submitted second quarter water information to the Division.

4.e Hydrologic Balance: Effluent Limitations

There was no discharge for the third quarter of 2013. Most of the sediment ponds are dry.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile for the third quarter of 2013 was inspected by a P.E. on November 24, 2013. No hazardous conditions were reported. I inspected these piles and did not see any hazardous conditions. The piles appear to be stable with no major signs of erosion.

8. Noncoal Waste

The permittee cleaned additional non-coal waste materials from the site.

15. Cessation of Operations

The site is inactive was it is related to mining activities. The site is used for trans-loading of crude oil.

16.a Roads: Construction, Maintenance, Surfacing

The permittee did road work on dirt roads outside the disturb area.

17. Other Transportation Facilities

Some of the train tracks were repair for the trans-loading of crude oil.

19. AVS Check

This function was conducted during the permit transfer process.